

To All Lamborghini Dealers and Licensed Service Point

From Customer Service Department

Subject Service Campaign - New layout for ground wiring

Group -

Date 06.09.05

Pages 3

Automobili Lamborghini S.p.A.

Subject

New layout for ground wiring

Model / VIN-Range

All Gallardo models until VIN 2624

Information to the field

In case you have a vehicle in the workshop, Lamborghini recommends changing the layout of the Gallardo ground wiring.

This modification must be performed on all cars involved at the next service.

Field solution

Change the layout of the ground wiring

Spare Parts

No spare parts needed



Warranty Claim data

You may find on Lamborghini Web Portal in the Warranty section "Available campaigns".

Campaign Code: L140-A09.05

Campaign Description: New layout for ground wiring

Cost Code: 50

Component Code: CCA0905

Trouble Code: 220

Labour Code: CCA0905100

Labour Time: 0.25 h

Your Area Manager is at your full disposal for further informations.

Best regards

Product Service




Necessary material

No materials needed.

Description of operations

- **1.1** Adopt all precautions to prevent car damages and to work safe.
- **1.2** Raise the car on the lift.
- **1.3** Disconnect the wiring on both sides sides and reconnect it positioned over the engine oil pipe as shown in the picture below.



The information and procedures published below are strictly confidential and intended exclusively for authorized operators and individuals. All copyrights are the property of Automobili Lamborghini S.p.A based on copyright law. The company reserves the right to make updates and modifications. The reprinting, reproduction, forwarding to unauthorized people and/or to third parties and partial or entire translation thereof are prohibited without written authorization from Automobili Lamborghini S.p.A.