

January 27, 2015

01381 Version 1

Warranty Extension: IMA Battery

AFFECTED VEHICLES

Year	Model	VIN Range
2009–11	Civic Hybrid	Check the iN VIN status for eligibility

BACKGROUND

To improve customer confidence, American Honda is extending the warranty coverage on all 2009–11 non-PZEV Civic IMA battery modules to match the PZEV warranty, which is 10 years or 150,000 miles, whichever comes first.

There is no change to the warranty on 2009–11 PZEV Civic IMA battery modules.

NOTE: The junction board is not covered under this warranty extension.

Model Year	Emission Type	Original Warranty	Current Warranty
2009	FED (40 State), OR/PA	8 year/80,000 miles	10 year/150,000 miles
2009	PZEV	10 year/150,000 miles	10 year/150,000 miles
2010	FED (40 State), OR/PA	8 year/100,000 miles	10 year/150,000 miles
2010	PZEV	10 year/150,000 miles	10 year/150,000 miles
2011	FED (40 State), OR/PA	8 year/100,000 miles	10 year/150,000 miles
2011	PZEV	10 year/150,000 miles	10 year/150,000 miles

CUSTOMER NOTIFICATION

Owners of affected vehicles will receive a notification of this warranty extension.

Do an iN VIN status inquiry to make sure the vehicle is shown as eligible.

CORRECTIVE ACTION

Diagnose the IMA battery problem and replace the IMA battery if needed.

PARTS INFORMATION

Part Name	Part Number	Quantity
IMA Battery	1D070-RMX-A90RM	1

WARRANTY CLAIM INFORMATION

Operation Number	Description	Flat Rate Time	Defect Code	Symptom Code	Template ID	Failed Part Number
1185A8	Diagnose and replace the IMA battery (includes transferring the junction board to the new IMA battery).	1.6 hrs.	5K900	JL400	15-006A	1D010-RMX-A02

Skill Level: Repair Technician

CUSTOMER INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by “do-it-yourselfers,” and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.

DIAGNOSIS

Diagnose the problem with the IMA battery. Refer to the electronic service manual and enter keywords **HOW TO**, then select **How to Troubleshoot the IMA system**.

REPAIR PROCEDURE

Replace the IMA battery; refer to the electronic service manual.

NOTE:

- You must be fully certified in the Electrical Fundamentals map, and have completed training modules MAC 10 and 12 on the Electrical Systems map, in order to do junction board and IMA battery module replacements.
- For more information about ordering and replacing the IMA battery, refer to Service Bulletin 10-061, *IMA Battery Exchange Program*, and 12-048, *Junction Board Replacement (IMA Battery Module Replacement and Transfer of Junction Board)*.

END