

American Honda Motor Co., Inc. 1919 Torrance Blvd., P.O. Box 2215 Torrance, CA 90509-9870

### CSC-10052082-6259

June 2014

RE: 2014 RLX

Dear Acura RLX Owner:

#### What is the reason for this notice?

Our records indicate that a PRODUCT UPDATE has not been completed on this vehicle; refer to the address card for the affected VIN. In some vehicles, the software for your audio or audio-navigation unit will need to be updated to repair several known audio, HandsFreeLink, and navigation system bugs.

#### What should you do?

Please contact any authorized Acura dealer to have your vehicle updated. This work will be done *free of charge*.

#### If you have questions

If you have any questions about this notice, or you need assistance locating a dealer, contact Acura Client Relations at 800-382-2238 and select option 4. You may also find this information at <a href="https://www.owners.Acura.com">www.owners.Acura.com</a>.

We apologize for any inconvenience this product update may cause you.

Sincerely,

American Honda Motor Co., Inc. Acura Automobile Division

NOTICE: If this is a leased vehicle, please forward this notice to the lessee.

FOR DEALER USE ONLY: REFERENCE SVC BULLETIN #13-008

S91

#### IMPORTANT: PRODUCT ADVISORY ENCLOSED PLEASE OPEN IMMEDIATELY

PLEASE DELIVER TO REGISTERED OWNER

S91

VEHICLE IDENTIFICATION ▶ NUMBER

# PRINTED PERF▼ PLEASE DETACH, SIGN BELOW AND PLACE IN RETURN ENVELOPE ▼

## INFORMATION CHANGE CARD

INFORMATION CHANGE CARD		
PLEASE PROVIDE NAME AND ADDRESS CORRECT	TIONS ON THE REVERSE SIDE	
	▼VEHICLE IDENTIFICATION NUMBER  PLEASE SIGN AND RETURN THIS CARD  ONLY IF YOU HAVE MADE CHANGES	S91
I no longer own the vehicle. It was:  Sold(print name and address of new owner on reverse, if known)  Exported  Destroyed  Stolen  Lease expired, vehicle returned.  Other:	Nota: Si usted necesita esta información en español por favor comuníquese con Servicio al Cliente al 800-999-1009 y seleccione la opción 4.	

Signature: X

Date: