

To All Lamborghini Dealers and Licensed Service Point

From Customer Service Department

Subject Rear Spoiler Tierod Clip

Group 8.27.00 Date 22/12/2011

Page 4

Subject

Rear Spoiler Tie rod Clip.

Model/VIN Range.

All Gallardo <u>Coupe</u>, LP 570 version, MY09; MY10 and MY 11 from VIN 9LA06526 to VIN BLA10676.

<u>Warning:</u> some vehicles included in this VIN range may not be affected, so check carefully on the Lamborghini WEB Portal (at the section named VIN Info) if the cars in your workshop or in your eventual stock are effectively affected before performing any other operation.

Information to the field

As a continuous product monitoring, , Automobili Lamborghini Spa has found that in rare cases the rear spoiler might be stuck in raised position as consequence of the detachment of the tierod which drives it.

Field solution

Fit the clip onto the rear spolier tierod.

Spare parts

P/N	Description	Q
400860349	Clips	2

The information and procedures published below are strictly confidential and intended exclusively for authorized operators and individuals. All copyrights are the property of Automobili Lamborghini S.p.A based on copyright law. The company reserves the right to make updates and modifications. The reprinting, reproduction, forwarding to unauthorized people and/or to third parties and partial or entire translation thereof are prohibited without written authorization from Automobili Lamborghini S.p.A.



Warranty Claim data

The warranty reimbursement request for this rework action will be managed by the following standard Warranty Claim procedures

Campaign Code: L714-A.03.11

Campaign Description: Rear spoiler tie rod clips

Cost Code: 50

Component Code: CCA0311

Trouble Code: 220

Labour Code: CCA0311100

Labour Time: 0,1 h.

Remember to fill all data in the section "Service and Recall Campaign" in the Warranty booklet of the vehicle as shown below.

Service/Service Richlamo/Rückruf	Service/Service Richiamo/Rückruf
Service/Service Recell/Roppel Llamada a Taller	Service/Service Recall (Rappel Servicio
Numero/Numere Number/Numero Numero	Numerofikurumer Number/Numéro Número
Data/Datum/Date/Date/Fecha	Data/Datum/Date/Date/Fecha
Data rijenzatione/Reparaturdatum Repair Data/Dek de réparation Fecha reparación	Data ricarazione/Reparaturdatum Recolif Data Date de reparation Fecilia reparación
Essquito dal Concessionaria / Ausgellührt von der Vertragswerkstatt / Done by the Dealer Effectué par le concessionnaire / Efectuado por el Concesionario Firma / Unterschrift / Signature / Signature / Firma	Exegulo dal Concessionario / Ausgelührt von der Vertragswerkstatt / Done by the Dealer Effectivé par le concessionnaire / Effectivado por el Concessionario Firma / Unitersichrifit / Signature / Signature / Firma
Service/Service Service/Service Richiamo/Rückruf Recall/Rappel Llamada a Taller	Service/Service Richlamo/Rockruf Service/Service Recall/Rappel Servicio Llamada a Taller
Numero (Numero Numero (Numero Numero	Numero/Nummer Number/Numero Numero
Deta/Dotum/Date/Date/Fecha	Date/Datum/Date/Date/Fecha
Data riparazione/Reparaturdatum Repair Data/Date de régaration	Data riparazione/Reparaturdatum Repair Data/Date de réparation

The information and procedures published below are strictly confidential and intended exclusively for authorized operators and individuals. All copyrights are the property of Automobili Lamborghini S.p.A based on copyright law. The company reserves the right to make updates and modifications. The reprinting, reproduction, forwarding to unauthorized people and/or to third parties and partial or entire translation thereof are prohibited without written authorization from Automobili Lamborghini S.p.A.



Workshop instructions

Preliminary operation

Operation to be carried out at cold engine.
Open the engine hood.

Clamp installation.



The information and procedures published below are strictly confidential and intended exclusively for authorized operators and individuals. All copyrights are the property of Automobili Lamborghini S.p.A based on copyright law. The company reserves the right to make updates and modifications. The reprinting, reproduction, forwarding to unauthorized people and/or to third parties and partial or entire translation thereof are prohibited without written authorization from Automobili Lamborghini S.p.A.



4	Fit the clip with the short side placed toward the spoiler lifter mechanism as shown in the beside picture.	Short side
5	Rotate outward the clip until touching the hood plate. Repeat the same operation on both sides.	
6	Close the engine hood	

Please contact your Area Manager for any further information.

Yours sincerely

Customer Service.

The information and procedures published below are strictly confidential and intended exclusively for authorized operators and individuals. All copyrights are the property of Automobili Lamborghini S.p.A based on copyright law. The company reserves the right to make updates and modifications. The reprinting, reproduction, forwarding to unauthorized people and/or to third parties and partial or entire translation thereof are prohibited without written authorization from Automobili Lamborghini S.p.A.