

## ***SERVICE MANUAL BULLETIN***

This Service Manual Bulletin is prepared by the Publications Department of New Flyer Industries Canada ULC. Refer to details below.

### **SMB-146**

ISSUE DATE: Apr 27 2015

<b>APPLICABILITY</b>					
<b>VEHICLE LENGTH</b>	<input type="checkbox"/> 30ft.	<input type="checkbox"/> 35ft.	<input type="checkbox"/> 40ft.	<input type="checkbox"/> 60ft.	<input checked="" type="checkbox"/> ALL
<b>VEHICLE TYPE</b>	<input type="checkbox"/> High Floor	<input type="checkbox"/> Low Floor	<input type="checkbox"/> Invero®	<input checked="" type="checkbox"/> Xcelsior®	<input type="checkbox"/> ALL
<b>FUEL TYPE</b>	<input checked="" type="checkbox"/> Diesel	<input type="checkbox"/> Electric	<input type="checkbox"/> CNG	<input type="checkbox"/> LNG	<input type="checkbox"/> ALL
	<input checked="" type="checkbox"/> Diesel/Electric	<input type="checkbox"/> Gas/Electric	<input type="checkbox"/> Fuel Cell		
<b>SUBJECT</b>	DEF Tank Drain Plug				
<b>SECTION TITLE</b>	4 - ENGINE SYSTEM				
<b>DETAILS</b>	<p>This bulletin provides revised information on the torque value for the DEF tank drain plug.</p> <p>Clean and install the drain plug. Torque to 48in-lb. (5.4 Nm).</p> <p>This information supersedes all prior information on this subject already provided in your New Flyer Service Manuals. Make this Service Bulletin available to service personnel to inform them of changed information.</p>				