



Bulletin No.: PIT5326B
Published date: 12/6/2017

Preliminary Information

PIT5326B Installation Of Electrical Aftermarket Accessories (Battery Ignition And Ground Connections)

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 1500	2014	All	All	All	All
Chevrolet	Silverado	2015 - 2018	All	All	All	All
GMC	Sierra 1500	2014	All	All	All	All
GMC	Sierra	2015 - 2018	All	All	All	All

Supersession Statement

This PI was superseded to add the 2018 models. Please discard PIT5326A.

Condition / Concern

Upfitters/owners may question where they can install their aftermarket electrical accessories.

Provisions have been provided for the installation of electrical accessories without splicing or cutting into the factory wiring harness. Please reference the latest version of GM Upfitter Integration Bulletin 115 for this information. It can be found at <http://www.gmupfitter.com/>, under the "Technical Bulletin" Tab and then "Show all bulletins."

IMPORTANT: It is very important that electrical accessories be installed properly and not spliced or cut into the factory wiring harness.



© 2016 General Motors. All Rights Reserved.