



Preliminary Information

PIP5659 2019 8L90 MQE Automatic Transmission Turbine And Stator Shaft Seal Installation Tools Availability

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 1500 (New Model)	2019	All	All	All	MQE
GMC	Sierra 1500 (New Model)	2019	All	All	All	MQE

Involved Region or Country	North America
Additional Options (RPO)	None
Condition	Technician's may notice that during the installation of the front turbine shaft seals or the rear stator shaft seals for the 8L90 (MQE) automatic transmission the tools listed in SI cannot be used.
Cause	Changes have been made to the turbine shaft and the stator shaft.

Correction:

Dealers may borrow the prototype turbine shaft and stator shaft tools by contacting Brian Echtenaw at Bosch at 1-800-468-6657.

The tools numbers needed are:

- DT-50910-3A Turbine Shaft Seal Installer
- DT-50912-3A Stator Shaft Seal Installer

The production tools will be available for dealer purchase soon.

Version History

Version	1
Modified	07/11/2019 - Created on.

