

WORK DESCRIPTION FOR FIELD MEASURE

Enclose charging cable as a service measure

Work procedure

1. Enclose Mode 2 charging cable as a service measure.

i Please ask the customer if they have already received the missing charging cable.

i Some customers have received this charging cable from the dealer earlier at no cost. In this case, mark the field measure in the system as having been processed for the vehicle.

The charging cable **may be added as a service measure only** if the customer **has not yet received one**.

Parts

Quantity	Designation	Part no.
As required (1) *	Mode 2 charging cable	*

* **The replacement parts must be determined according to the equipment variant for the vehicle identification number via the parts process in the Xentry Portal.**

Operation text and flat rate

Operation no.	Operation text	Flat rate	Accounting no./ damage code
12-1607	Enclose charging cable as a service measure	0.1 h	06 990 12
