



10022963

# Service Bulletin

File In Section: 08 - Body and Accessories

Bulletin No.: 07-08-47-004A

Date: August, 2007



## INFORMATION

**Subject:** Information on Body Control Module (BCM) Grounds

**Models:** 2006–2008 Buick Lucerne  
 2008 Buick Enclave  
 2006–2008 Cadillac DTS, Escalade Models, SRX  
 2008 Cadillac CTS  
 2006–2007 Chevrolet Monte Carlo  
 2006–2008 Chevrolet Impala  
 2007–2008 Chevrolet Avalanche, Equinox, Silverado, Suburban, Tahoe  
 2007–2008 GMC Acadia, Sierra, Yukon, Yukon XL, Yukon Denali,  
 Yukon Denali XL  
 2007–2008 Pontiac Torrent  
 2007–2008 Saturn OUTLOOK  
 2008 Saturn VUE

**This bulletin is being revised to add models and to update the models to 2008. Please discard Corporate Bulletin Number 07-08-47-004 (Section 08 — Body & Accessories)**

The purpose of this bulletin is to inform dealers of the importance of **properly installing and verifying BCM grounds** whenever a BCM is serviced or replaced.

**Notice:** Prior to disconnecting a BCM ground, the negative battery cable should be disconnected, or all other connections to the BCM should be disconnected first. Failure to disconnect all powered connections prior to disconnecting the ground may result in damage to the BCM.

If the BCM grounds are not correctly installed, damage to the BCM may occur. Other systems controlled by the BCM may also become inoperative or intermittent:

- Interior lighting
- Remote keyless entry
- Door locks
- Power windows and mirrors

To verify BCM ground, first visually inspect the ground connection. Then use a digital multimeter (such as J 39200, J 39688 or equivalent) to perform a ground check from connector C3 or X3 at pin locations 1 and 5 of the BCM to ground (with the connector C3 or X3 disconnected from the BCM).

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



**WE SUPPORT VOLUNTARY  
 TECHNICIAN  
 CERTIFICATION**