

Published
ID: 112634

Message

Target

Options

Save / Deny

Done

Request

Communication

Publish Dates

- The Start Date is when the communication will be visible to dealers in DCMail.
- The End Date is when the communication will no longer be visible to dealers in DCMail.
- NOTE: End Dates are limited to one (1) year from the Start Date. If you wish to lengthen the End Date, you may extend it at any time after publish.

Start Date 6/3/2026 7:00 AM

End Date 6/24/2026 11:55 PM

Note: All times are EST

Extend End Date

Title

What will display in DCMail for dealers to click on.
TIP: Keep titles short, but specific and eye catching.

HANDLE - DOOR PULL AND PANEL - FRONT DOOR TRIM : POIGNÉE - TIRE-PORTE ET PANNEAU - GARNITURE DE PORTE AVANT : MANIJA - TIRADOR DE PUERTA
Y PANEL - EMBELLECEDOR DE LA PUERTA - DELANTERA

Flagged for Reporting Agency

NO

Communication Summary

To increase search capability and visibility of your communication, please provide a brief summary or your message (140 characters max). This will display when dealers hover over your communication.

HANDLE - DOOR PULL AND PANEL - FRONT DOOR TRIM : POIGNÉE - TIRE-PORTE ET PANNEAU - GARNITURE DE PORTE AVANT : MANIJA - TIRADOR DE PUERTA
Y

Message

The body of your communication. Use the formatting toolbar above to format text, insert tables, pictures, and/or hyperlinks.

Click Edit > Attach File to attach documents

IMPORTANT NOTES:

- Pictures must have unique file names. If you receive an error message when uploading a picture, it means the file name has already been chosen. Simply change your file name and try again.
- Communications cannot exceed more than 12MB; this includes images and text, and all attachments.

You have been identified as either having stock on hand or in transit to your dealership.

Please check and return suspect stock of part numbers: **6RN86TX7AB** and **7ZB44TX7AA**. Please refer to QIR attachment.

Please return all parts back to your facing depot using **Return Code 02**, before 24th June 2026.

For replacement place new orders.

Return any open orders in process too. Direct questions regarding returns via email to mopardmail@stellantis.com.



Quality Inspection Request

3-June-2026

HANDLE - DOOR PULL AND PANEL - FRONT DOOR TRIM

Suspect Part Identification

Part numbers:

6RN86TX7AB and 7ZB44TX7AA

Built date code location:

Built date code shown

20251110: YYYYMMDD

10TH November 2025

Part in picture shown is not suspect.

Part in picture below is not suspect

PART (P) 7ZB44TX7AA		SHIP FROM Antolin Shelby 52888 SHELBY PARKWAY 48315 SHELBY TOWNSHIP(US)	
Qty (Q) 1		PART NUMBER DESCRIPTION FRT RH TRADESMAN BLACK	
SUPLR ID CUST 25779		CHANGE LETTER	SAFETY
SERIAL(JS) 220334436		DATE MFG 20251110	
		DOCK LOC	DROP ZONE 03117

Suspect parts: Parts built before **20250520** (20th May 2025) are suspect parts.



Demande d'inspection de la qualité
POIGNÉE - TIRE-PORTE ET PANNEAU - GARNITURE DE PORTE AVANT

3-Juin-2026

Identification de la pièce suspecte

Les Numéro de pièce: 6RN86TX7AB et 7ZB44TX7AA Emplacement du code de date de construction Code de date de construction affiché 20251110: AAAAMMJJ 10 novembre 2025 La pièce représentée sur l'image n'est pas suspecte.	La pièce représentée sur l'image ci-dessous n'est pas suspecte. 
---	---

Pièces suspectes: Les pièces construites avant le **20250520** (20 mai 2025) sont des pièces suspectes



Solicitud de inspección de calidad
MANIJA - TIRADOR DE PUERTA Y PANEL - EMBELLECEDOR DE LA PUERTA DELANTERA

3 de junio de 2026

Identificación de la pieza sospechosa

Números de pieza: 6RN86TX7AB y 7ZB44TX7AA. Ubicación del código de fecha de construcción: Se muestra el código de fecha de construcción 20251110: AAAAMMDD 10 de noviembre de 2025 La pieza mostrada en la imagen no es la sospechosa.	La pieza que aparece en la imagen de abajo no es sospechosa. 
--	--

Partes sospechosas: Las piezas construidas antes de **20250520** (20 de mayo de 2025) son piezas sospechosas.

