

Aluminum Top Tank Radiator

Concern: TitanX Radiator TXE 1003850D Failures

Affected Models:
4th Generation Cascadia

Root Cause: Top tank cracking

Correction: Changeover from original top tank plastic to new plastic material in October 2023

The TitanX replacement for TXE 1003850D is **TXE 1003850E**. The DTNA service part is 05-37217-080

*** You may find early parts shipped/boxed as TXE 1003850D, but are correct p/n ending in 'E'*

Production Changeover: April 2026 – Aluminum top tank at TitanX

