

9100852

06/30/2026

MY 23-25 GG 20-24 BV 24-25 MV 24-25
GC

GPOP - Issue Review System

Part Number: 68504352A\$

Part Description: long block

Issue When long block is received, inspection needs to be performed per SOL S2609000010
Description: before the repair begins. If the block machining is not complete according to information in SOL, a new long block will need to be ordered.