

Published
ID: 113271

Message

Target

Options

Save / Deny

Clone

Request

Communication

Publish Dates

- The Start Date is when the communication will be visible to dealers in DCMail.
- The End Date is when the communication will no longer be visible to dealers in DCMail.
- NOTE: End Dates are limited to one (1) year from the Start Date. If you wish to lengthen the End Date, you may extend it at any time after publish.

Start Date 7/7/2026 7:00 AM

End Date 7/28/2026 11:55 PM

Note: All times are EST

Title

What will display in DCMail for dealers to click on.
TIP: Keep titles short, but specific and eye catching.

CORE – HEATER : CORE – CHAUFFAGE : NÚCLEO – CALENTADOR

Flagged for Reporting Agency

NO

Communication Summary

To increase search capability and visibility of your communication, please provide a brief summary or your message (140 characters max). This will display when dealers hover over your communication.

CORE – HEATER : CORE – CHAUFFAGE : NÚCLEO – CALENTADOR

Message

The body of your communication. Use the formatting toolbar above to format text, insert tables, pictures, and/or hyperlinks.

Click Edit > Attach File to attach documents

IMPORTANT NOTES:

- Pictures must have unique file names. If you receive an error message when uploading a picture, it means the file name has already been chosen. Simply change your file name and try again.
- Communications cannot exceed more than 12MB; this includes images and text, and all attachments.

You have been identified as either having stock on hand or in transit to your dealership.

Please check and return suspect stock of part numbers: **68301874AA**. Please refer to QIR attachment.

Please return all parts back to your facing depot using **Return Code 02**, before 28th July 2026.

For replacement place new orders.

Return any open orders in process too. Direct questions regarding returns via email to mopardmail@stellantis.com.



Quality Inspection Request CORE – HEATER Suspect Part Identification

7-July-2026

Part numbers: 68301874AA

Built date code location:

Built date code shown

JAN 08 2026 : MON DD YYYY

8th January 2026

Part in picture shown is not suspect.

Part in picture below is not suspect



Suspect parts: Parts built before **JAN 01 2026** (1st January 2026) are suspect parts.



Demande d'inspection de la qualité
CORE – CHAUFFAGE

7-Juillet-2026

Identification de la pièce suspecte

Les Numéro de pièce: 68301874AA

Emplacement du code de date de construction

Code de date de construction affiché

JAN 08 2026 : MMM JJ AAAA

8 janvier 2026

La partie visible sur la photo n'est pas suspecte.

La partie visible sur l'image ci-dessous n'est pas suspecte.



Pièces suspectes: Les pièces construites avant le **JAN 01 2026** (1er janvier 2026) sont des pièces suspectes



Solicitud de inspección de calidad
NÚCLEO – CALENTADOR

7 de julio de 2026

Identificación de la pieza sospechosa

Números de pieza: 68301874AA

Ubicación del código de fecha de construcción:

Se muestra el código de fecha de construcción

JAN 08 2026 : MMM/DD/AAAA

8 de enero de 2026

La pieza que aparece en la imagen no es la sospechosa.

La parte que se muestra en la imagen de abajo no es sospechosa.



Partes sospechosas: Las piezas construidas antes de **JAN 01 2026** (1 de enero de 2026) son piezas sospechosas.