

GPOP - Issue Review System

Part Number: 1UJ81GW7A\$, 1UJ81JSCA\$, 1UJ81KARA\$, 1UJ81KCLA\$,
1UJ81KFPA\$, 1UJ81KGZA\$, 1UJ81KXJA\$, 1UJ81LAUA\$,
1UJ81MBJA\$, 1UJ81NRVA\$, 1UJ81NVPA\$, 1UJ81PDNA\$,
1UJ81PR4A\$, 1UJ81PWQA\$, 1UJ81RPXA\$, 1UJ81RUWA\$,
1UJ81SSEA\$, 1UJ81WCGA\$, 1UJ81ZG9A\$, 1UJ81ZR6A\$,
1UJ86GW7A\$, 1UJ86JSCA\$, 1UJ86KARA\$, 1UJ86KCLA\$,
1UJ86KFPA\$, 1UJ86KGZA\$, 1UJ86KXJA\$, 1UJ86LAUA\$,
1UJ86MBJA\$, 1UJ86NRVA\$, 1UJ86NVPA\$, 1UJ86PDNA\$,
1UJ86PR4A\$, 1UJ86PWQA\$, 1UJ86RPXA\$, 1UJ86RUWA\$,
1UJ86SSEA\$, 1UJ86WCGA\$, 1UJ86ZG9A\$, 1UJ86ZR6A\$,
6NV561ARA\$, 6NV561AUA\$, 6NV561BJA\$, 6NV561CLA\$,
6NV561FPA\$, 6NV561GZA\$, 6NV561PXA\$, 6NV561R4A\$,
6NV561RVA\$, 6NV561SCA\$, 6NV561UWA\$, 6NV561W7A\$,
6NV561WQA\$, 6NV561XJA\$, 6NV571ARA\$, 6NV571AUA\$,
6NV571BJA\$, 6NV571CLA\$, 6NV571FPA\$, 6NV571GZA\$,
6NV571PXA\$, 6NV571R4A\$, 6NV571RVA\$, 6NV571SCA\$,
6NV571UWA\$, 6NV571W7A\$, 6NV571WQA\$, 6NV571XJA\$

Part Description: Passive Entry O/S Dr Handle

Issue Prior to replacing an inoperative passive entry door handle, perform Star Online
Description: S2623000040.