

GPOP - Issue Review System

Part Number: 6PF69GW7A\$, 6PF69KXJA\$, 6PF69LPSA\$, 6PF69MBJA\$,
6PF69NRVA\$, 6PF69SSEA\$, 6PF69WASA\$, 6PF69WCQA\$,
6PF69WFJA\$, 6PF69WHCA\$, 6PF69WVBA\$, 6PF69ZB5A\$,
6XA88GW7A\$, 6XA88KXJA\$, 6XA88LPSA\$, 6XA88MBJA\$,
6XA88NRVA\$, 6XA88SSEA\$, 6XA88VCAA\$, 6XA88WASA\$,
6XA88WCQA\$, 6XA88WFJA\$, 6XA88WHCA\$, 6XA88WVBA\$,
6XA88ZB5A\$, 7BD70GW7A\$, 7BD70KXJA\$, 7BD70LPSA\$,
7BD70MBJA\$, 7BD70NRVA\$, 7BD70SSEA\$, 7BD70VCAA\$,
7BD70WASA\$, 7BD70WCQA\$, 7BD70WFJA\$, 7BD70WHCA\$,
7BD70WVBA\$, 7BD70ZB5A\$, 7BD71GW7A\$, 7BD71KXJA\$,
7BD71LPSA\$, 7BD71MBJA\$, 7BD71NRVA\$, 7BD71SSEA\$,
7BD71WASA\$, 7BD71WCQA\$, 7BD71WFJA\$, 7BD71WHCA\$,
7BD71WVBA\$, 7BD71ZB5A\$, 7KP81GW7A\$, 7KP81KXJA\$,
7KP81LPSA\$, 7KP81MBJA\$, 7KP81NRVA\$, 7KP81SSEA\$,
7KP81VCAA\$, 7KP81WASA\$, 7KP81WCQA\$, 7KP81WFJA\$,
7KP81WHCA\$, 7KP81WVBA\$, 7KP81ZB5A\$, 7KP82GW7A\$,
7KP82KXJA\$, 7KP82LPSA\$, 7KP82MBJA\$, 7KP82NRVA\$,
7KP82SSEA\$, 7KP82VCAA\$, 7KP82WASA\$, 7KP82WCQA\$,
7KP82WFJA\$, 7KP82WHCA\$, 7KP82WVBA\$, 7KP82ZB5A\$

Part Description: Passive Entry O/S Dr Handle

Issue Prior to replacing an inoperative passive entry door handle, perform Star Online
Description: S2623000040.