



RECALL CAMPAIGN BULLETIN

Reference:

NTB14-101a

Date:

January 21, 2016

VOLUNTARY SAFETY RECALL CAMPAIGN 2013 ALTIMA SECONDARY HOOD LATCH INSPECTION

CAMPAIGN ID #: R1413

APPLIED VEHICLES: 2013 Altima (L33)

This bulletin has been superseded by NTB16-011

**VOLUNTARY SAFETY RECALL CAMPAIGN
2013 – 2015 ALTIMA; HOOD LOCK ASSEMBLY REPLACEMENT**

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.