

From: Broadcast Messaging System
To: [DL-BMS Message Monitors](#)
Subject: MY18 4 Series Convertible Delivery Delay (F33 and F83)
Date: Friday, August 25, 2017 4:08:42 PM

Publish Date: August 25, 2017
From: National Automotive Sales
Expiration Date: October 31, 2017

DCSnet Message
Important



Subject: **MY18 4 Series Convertible Delivery Delay (F33 and F83)**

DELIVERY DELAY FOR MY18 4 SERIES CONVERTIBLE (F33 and F83)

Approximately 1200 MY18 4 Series Convertibles (F33 and F83) have been placed on delivery stop due to an issue with the front driver and passenger seat belts. See attached VDC Service Information bulletin 17B49 for more information.

Repairs will be prioritized in the following order:

1. Retailed vehicles
2. Customer sold in dealer inventory
3. Customer sold at the VDC
4. Stock in dealer inventory
5. Stock at the VDC.

Please communicate your most pressing customer issues to your Regional Distribution teams and we will do our best to prioritize those customers.

Repairs will begin early to mid-September and continue through October as parts become available.

National Automotive Sales

Attachments:



[17B49_Bulletin\[81a40220\].pdf](#)



[17B49_Bulletin\[81a40220\].pdf](#)

Recipients: BMW Passenger Cars, CC-All
BMW Passenger Cars, All Offerings, All Regions, All Areas, All Departments, All Personnel



REPLACE BOTH FRONT SEAT BELTS

MODEL

F33 4 Series Convertible
F83 M4 Convertible

SITUATION

The restraining function of the seat belts may not be adequate in case of heavy braking.

CAUSE

The seat belts may have a manufacturing error.

CORRECTION

Replace both front seat belts.

PROCEDURE

Replace left and right front seat belt as per “**REP 72 11 001 Removing and installing front left seat belt and REP 72 11 002 Removing and installing front right seat belt**”.

PARTS INFORMATION

Part Number	Description	Quantity
07 14 7 122 476	Fillister head screw	2
07 14 9 148 299	Fillister head screw	2
07 14 9 321 690	Fillister head screw	10
07 14 9 156 955	Fillister head screw	4
72 11 7 318 345	Upper belt front left black	1
72 11 7 318 346	Upper belt front right black	1
OR		
72 11 7 318 347	Upper belt front left Veneto beige	1
72 11 7 318 348	Upper belt front right Veneto beige	1
Only if required		
07 14 7 398 148	Tilting captive nut	2
41 00 7 243 852	Fillister head screw	2
72 11 6 985 527	Socket head cap screw with shoulder	2
	Covering cap	2

WARRANTY INFORMATION

Defect Code: 00 72 90 01 00

Labor Operation:	Labor Allowance:	Description:
XX XX XXX*	FRU	XXXXXXXXXXXXXXXXXXXXXXX

*- Data is not available yet. It will be added as soon as it becomes available.