

0985 N 900 W • Shipshewana, IN 46565 e-mail: kz@kz-rv.com • www.kz-rv.com Phone: 260.768.4016 • Fax: 260.768.4017

IMPORTANT SAFETY RECALL

KZRV, L.P.

NHTSA Recall Number 17V-Transport Canada Recall Number 2017-

Date: December 1, 2017

TO: KZRV Dealer

Problem

The vehicles subject to his recall were built with a standard 110V electrical outlet rather than a Ground Fault Circuit Interrupter (GFCI) outlet in the outside kitchen compartment. An electrical shock can result injury or death.

RANGE OF VEHICLES INVOLVED:

- 2017 & 2018 Connect KZRV Travel Trailers

WARRANTY REIMBURSEMENT:

A notice of this recall has been sent to affected retail owners. A copy of the Owner's letter is included for your review. They may request that you complete the repair. If so, please follow the warranty reimbursement procedure. If the unit and/or units are in your inventory, or if you are requested to perform the repair for the retail customer, please complete the advised repair and send in a warranty claim referencing this recall number for reimbursement. The time allowed for repair is 120 minutes.

SERVICE ACTION:

Replace the outlet with a GFCI outlet.

encl. - Owners Letter

Mark Owens

Director of Service and Warranty Administration