

Recall Quarterly Report**18E-008**

Manufacturer Name : Whammerdyne Inc.
NHTSA Recall No. / MFR Recall No. : 18E-008 /
Recall Subject : Vent System may Seep Fuel
Owner Notification Beginning Date : MAR 23, 2018
Owner Notification End Date: MAR 23, 2018



| Report # | Submission Date | Report Quarter | Recall Population | Total Remedied | Total Unreachable | Total Removed |
|----------|-----------------|----------------|-------------------|----------------|-------------------|---------------|
| 5 | JUN 25, 2019 | 2019-1 | 1,000 | 100 | 0 | 100 |
| 4 | JUN 25, 2019 | 2018-4 | 1,000 | 79 | 0 | 79 |
| 3 | DEC 10, 2018 | 2018-3 | 1,000 | 28 | 1 | 18 |
| 2 | DEC 10, 2018 | 2018-2 | 1,000 | 0 | 0 | 0 |
| 1 | MAY 01, 2018 | 2018-1 | 1,000 | 0 | 260 | 0 |

This Document Last Updated : JUN 25, 2019

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.