## OMB Control No.: 2127-0004

## **Recall Quarterly Report**

18E-009

Manufacturer Name: Whammerdyne Inc.
NHTSA Recall No. / MFR Recall No.: 18E-009 /
Recall Subject: Vent System may Seep Fuel

**Owner Notification Beginning Date:** MAR 23, 2018

Owner Notification End Date: MAR 23, 2018



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
2	NOV 20, 2018	2018-2	1,000	8	0	8
1	MAY 01, 2018	2018-1	1,000	0	260	0

This Document Last Updated: NOV 23, 2018

## **Definitions:**

 $Report\ Quarter:\ The\ quarter\ the\ manufacturer\ is\ reporting\ recall\ completion\ figures\ (e.g.\ 2012-3\ means\ the\ 3^{\bf rd}\ quarter\ of\ 2012).$ 

Recall Population: The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.