OMB Control No.: 2127-0004

# Part 573 Safety Recall Report

## 18E-009

**Manufacturer Name:** Whammerdyne Inc.

**Submission Date:** FEB 03, 2018 **NHTSA Recall No.:** 18E-009

**Manufacturer Recall No.:** NR



#### **Manufacturer Information:**

Manufacturer Name: Whammerdyne Inc.

Address: 2014 Holland Avenue

Unit 323 Port Huron MI 48060

Company phone: 8882166033

## **Population:**

Number of potentially involved: 1,000 Estimated percentage with defect: 5 %

## **Equipment Information:**

Brand / Trade 1: II MUCH

Model: VSB Part No.: 100016 Size: NR

**Function**: Vent System

**Descriptive Information:** Entire population

Production Dates: JAN 01, 2015 - JAN 31, 2018

#### **Description of Defect:**

Description of the Defect: Fuel seepage reported at joint.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: Fuel in the presence of ignition source could cause fire.

Description of the Cause : Adhesive joint not curing properly Identification of Any Warning Visual indication of fuel or fuel odor.

that can Occur:

#### **Supplier Identification:**

#### **Component Manufacturer**

Name: NR Address: NR NR

The information contained in this report was submitted pursuant to 49 CFR §573

Country: NR

#### **Chronology:**

28 January 2018 Contact from customer regarding possible defect similar to occurrence observed in PN 100016.

29 January 2018 Analysis determined a recall should be initiated.

### **Description of Remedy:**

Description of Remedy Program: Effected units will be replaced with redesigned units at no charge.

How Remedy Component Differs The II MUCH brand VSB, PN 100016 will be redesigned and a new part

from Recalled Component: number assigned and permanently inscribed on the product.

Identify How/When Recall Condition Still under investigation.

was Corrected in Production:

#### **Recall Schedule:**

Description of Recall Schedule: As soon as practicable.

Planned Dealer Notification Date : NR - NR Planned Owner Notification Date : NR - NR

#### **Purchaser Information:**

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name: NR

Address: NR

NR

Country: NR

Company Phone: NR

<sup>\*</sup> NR - Not Reported