OMB Control No.: 2127-0004

# Part 573 Safety Recall Report

## 18V-099

**Manufacturer Name:** Halcore Group, Inc.

**Submission Date:** MAR 09, 2018

NHTSA Recall No.: 18V-099

**Manufacturer Recall No.:** NR



#### **Manufacturer Information:**

Manufacturer Name: Halcore Group, Inc.

Address: 3800 McDowell Road

Grove City OH 43123

Company phone: 999

## **Population:**

Number of potentially involved : 7,574 Estimated percentage with defect :  $100\,\%$ 

#### **Vehicle Information:**

Vehicle 1: 2011-2018 American Emergency Vehicl Traumahawk Ambulance

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style : ALL Power Train : NR

Descriptive Information: Customer reports of the Vanner Inc battery isolator module overheating in six

vehicles that were produced May 5, 2017 through August 28, 2017.

Production Dates: NOV 15, 2011 - MAR 06, 2018

VIN Range 1 : Begin : NR End : NR Not sequential

#### **Description of Defect:**

Description of the Defect: Vanner Inc battery isolator module overheating.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: Vanner Inc 52-20 battery isolator module overheating can cause equipment

circuitry failure & possibly fire.

Description of the Cause: 2/8/2018 Per Vanner Inc the root cause evaluation is in process.

Identification of Any Warning Inoperable on-board equipment, automotive breaker clicking, discoloring,

that can Occur: deformed component and or smell.

## **Supplier Identification:**

#### **Component Manufacturer**

Name: Vanner Inc

Address: 4282 Reynolds Dr.

Hilliard OHIO 43026

**Country: United States** 

### **Chronology:**

December 1, 2017 one customer reported issue with two units, February 2018 two separate customers experience component issue. All trucks were produced May 5, 2017 through August 28, 2017. Vanner Inc 52-20 battery isolator modules were sent to Vanner Inc for identification of root cause.

## **Description of Remedy:**

Description of Remedy Program: NR

How Remedy Component Differs NR

from Recalled Component:

Identify How/When Recall Condition NR

was Corrected in Production:

#### **Recall Schedule:**

Description of Recall Schedule: NR

Planned Dealer Notification Date : NR - NR Planned Owner Notification Date : NR - NR

\* NR - Not Reported