

Part 573 Safety Recall Report

18V-196

Manufacturer Name : Winnebago Industries, Inc**Submission Date :** APR 18, 2018**NHTSA Recall No. :** 18V-196**Manufacturer Recall No. :** Recall 149**Manufacturer Information :****Population :**

Manufacturer Name : Winnebago Industries, Inc

Number of potentially involved : 908

Address : PO BOX 152
605 W. Crystal Lake Rd. Forest City IA
50436

Estimated percentage with defect : 100 %

Company phone : 1-641-585-3535

Vehicle Information :

Vehicle 1 : 2018-2019 Winnebago Intent

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Population is first production unit thru first good S/N 54860

Production Dates : MAY 25, 2017 - MAR 07, 2018

VIN Range 1 : Begin : NR

End : NR

☐ Not sequential**Description of Defect :**

Description of the Defect : The exterior rear view mirror(s) may have been installed incorrectly. The top mounting screws may not have engaged into the metal located in the sidewall for the mirror to mount to.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : The mirror(s) may fall off the vehicle going down the road.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR
NR
Country : NR

Chronology :

1-5-18 Drive-a-way company notified us that a mirror fell off while being delivered. 2-21-18 and 2-23-18 the drive-a-way company notified us that a mirror was loose during delivery. Internal audit was done followed by Hold Notice 680 was issued on 3-14-18. On 3-22-18 the safety committee meet and determined this is a recallable issue. 3-26-18 submitted this notice to the NHTSA portal.

Description of Remedy :

Description of Remedy Program : Check the location of the mirror. If location is outside the target area, remove and reinstall the mirror in the correct location.

How Remedy Component Differs from Recalled Component : none - same components (location issue only)

Identify How/When Recall Condition was Corrected in Production : production uses a fixture to locate the mirror in the correct location.

Recall Schedule :

Description of Recall Schedule : owners and dealers involved in the recall, notifications going out April/May 2018

Planned Dealer Notification Date : APR 16, 2018 - APR 21, 2018

Planned Owner Notification Date : APR 30, 2018 - APR 30, 2018

* NR - Not Reported