



IC Bus, LLC  
2701 Navistar Drive  
Lisle, IL 60532 USA  
navistar.com

A NAVISTAR COMPANY

MAILED

JAN 30 2019

Compliance Dept.

JANUARY 2019

**IMPORTANT SAFETY RECALL 18520  
NHTSA RECALL NO. 18V-902**

This notice applies to your vehicle identified on the enclosed card.

Dear IC Bus Customer,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

IC Bus has decided that a defect which relates to motor vehicle safety exists in certain 2019 and 2020 CE school bus models built 12/04/2017 thru 03/29/2018 with feature code 0004JNU (Automatic; Hydraulic Brake System).

**REASON FOR THIS RECALL**

The brake pressure switch on these buses may become stuck which results in a false fault code and brake warning light.

**RISK TO MOTOR VEHICLE SAFETY**

There is no direct safety consequence because the brake system continues to function normally. However, in certain situations, a brake warning light on a school bus that is carrying students may require the driver to immediately pull over and transfer students to another bus which could cause hazards with students near the roadway for an indeterminate amount of time.

**DEFECT REMEDY**

The repair will involve inspecting the lot code on the brake pressure switch and replacing any switch found with the suspect lot code. Dealers have parts and instructions to repair your vehicle. The repair will be performed free of charge and take approximately 45 minutes to complete.

**ACTIONS YOU SHOULD TAKE**

If you own this vehicle, please schedule an appointment with any IC Bus dealer to have your vehicle repaired. You

can find your nearest dealer by calling 1-800-448-7825 or by using the dealer locator at <http://www.icbus.com>.

If you have already paid for repairs prior to this notice that corrected the defect, you may be eligible for reimbursement of certain repair expenses if they occurred 12/19/2017 thru 02/09/2019. Present your original repair paperwork and proof of payment to any IC Bus dealer and your eligibility will be reviewed. You may also submit a claim using the enclosed Request for Reimbursement card.

If you are the lessor of this vehicle, please forward a copy of this notice to the lessee within ten days to comply with federal regulations.

If you do not own this vehicle, please fill out and return mail the enclosed card so that you will not be contacted again about this recall.

**IF YOU NEED ASSISTANCE**

If you believe that IC Bus has failed to remedy the defect without charge or within a reasonable time, please follow the procedure described in the Owner Assistance Guide section in your Owner's Manual or call toll free 1-800-448-7825.

You may also submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave, SE, Washington, DC 20590; or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

IC Bus requests your prompt attention and patience regarding the correction of this defect and apologizes for any inconvenience this may cause you.

**IC Bus, LLC**