The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report

Manufacturer Name : MATRIX HEADGEAR LTD

Submission Date: NOV 08, 2019

NHTSA Recall No.: 19E-076

Manufacturer Information :

Manufacturer Recall No.: NR

Manufacturer Name : MATRIX HEADGEAR LTD Address : 20-22 Wenlock Road

London 00 N1 7GU Company phone : 07480735365

Equipment Information :

Brand / Trade 1:	Matrix Headgear
Model :	Alpha
Part No. :	Alpha
Size :	NR
Function :	Helmet
Descriptive Information :	This recall applies only to Alpha helmets manufactured in March 2019 that has a DOT Mark, The owner of the helmet can Identify affected helmet by looking inside padding, as the previous Model had a different logo on the padding, 2 both variations will be included in a separate sheet
Production Dates :	MAR 12, 2019 - APR 03, 2019

Description of Noncompliance :

Description of the Noncompliance :	1 The helmet retention system on the high-temperature sample separated while loaded. 2 Impact Attenuation Failure 3 correct Labeling Failure
FMVSS 1 :	567 - Certification
FMVSS 2 :	NR
Description of the Safety Risk :	Wearing a motorcycle helmet that does not meet DOT standards may, in the event of an accident, expose the user to an increased risk of personal injury or death
Description of the Cause :	NR
Identification of Any Warning that can Occur :	


RATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION

Number of potentially involved :

Estimated percentage with defect : 100 %

Population :

19E-076



25

Supplier Identification :

Component Manufacturer

Name :VEGA AVIATION PRODUCTS PVT. LTDAddress :Sy.No.230,231/2, NH4A Belagavi
Khanapur Road, Desur Belagavi FOREIGN STATES 590014Country :India

Chronology:

The noncompliance has been identified after a test carried out by NHTSA testing division

Description of Remedy :

Description of Remedy Program :	We Plan to Manufacture and test new Alpha helmets according to DOT compliance procedure and replace noncompliant helmets, in case Manufacturer unable to Pass helmets through the test we will reimburse an amount paid by the owner upon return of the faulty item, minus any postage/shipping fees
5	Any replacement helmet will be manufactured from the proper materials; high impact polycarbonate resin and properly labeled. Matrix is still in the process of investigating the circumstances of this nonconformance to ensure future Alpha helmets meet FMVSS 218.
Identify How/When Recall Condition was Corrected in Production :	

Recall Schedule :

Description of Recall Schedule :	matrix will notify all helmet owners as soon as we have confirmation from the manufacturer on the outcome of the investigation on the failure
	of the Alpha helmet, of the dot test for new helmets
Planned Dealer Notification Date :	NR - NR
Planned Owner Notification Date :	NR - NR

Purchaser Information :

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report

Name : NR Address : NR NR Country : NR Company Phone : NR

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573

19E-076