

# Part 573 Safety Recall Report

# 19V-237

**Manufacturer Name :** Curbtender**Submission Date :** MAR 26, 2019**NHTSA Recall No. :** 19V-237**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Curbtender

Address : 701 Performance Dr

Cedar Falls IA 50613

Company phone : 266-1721 ext 382

**Population :**

Number of potentially involved : 6

Estimated percentage with defect : 100 %

**Vehicle Information :**

Vehicle 1 : 2018-2018 Ford W/Curbtender F650/QT06

Vehicle Type : BUSES, MEDIUM &amp; HEAVY VEHICLES

Body Style : OTHER

Power Train : NR

Descriptive Information : There are 6 units that had these parts installed. Here are the body SN of each of the units. SN 19475, 19484, 19485, 19486, 19487 and 19488.

Production Dates : OCT 17, 2018 - OCT 17, 2018

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Defect :**

Description of the Defect : Curbtender part# 332-043-005 In various models of accessory brake lights for use with emergency vehicles. Specifically, depending on the specific wiring of the vehicle, these brake lights may illuminate when the brake pedal has not been pressed.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : This will give an indication that the vehicle is stopping when actually it isn't.

Description of the Cause : NR

Identification of Any Warning NR  
that can Occur :

**Supplier Identification :****Component Manufacturer**

Name : Whelen Engineering  
Address : 51 Winthrop Dr  
Chester 06475  
Country : NR

**Chronology :**

NR

**Description of Remedy :**

Description of Remedy Program : NR  
How Remedy Component Differs NR  
from Recalled Component :  
Identify How/When Recall Condition NR  
was Corrected in Production :

**Recall Schedule :**

Description of Recall Schedule : NR  
Planned Dealer Notification Date : NR - NR  
Planned Owner Notification Date : NR - NR

\* NR - Not Reported