



# IMPORTANT SAFETY RECALL

## Livin' Lite

NHTSA Recall Number 19V-307 Transport Canada Recall Number 2019-228

Date: May 15, 2019

TO: Livin' Lite Dealer

#### **Problem**

The vehicles subject to this recall were built with an awning arm that blocks a marked egress window. In an emergency situation, the owner may attempt to use this window and could result in being unable to escape from the unit resulting in personal injury or death.

#### **RANGE OF VEHICLES INVOLVED:**

• 2014 - 2017 Camplite

• 2014 – 2017 Bearcat

#### **WARRANTY REIMBURSEMENT:**

A notice of this recall has been sent to affected retail owners. A copy of the Owner's letter is included for your review. They may request that you complete the repair. If so, please follow the warranty reimbursement procedure. If the unit and/or units are in your inventory, or if you are requested to perform the repair for the retail customer, please complete the advised repair and send in a warranty claim referencing this recall number for reimbursement. The time allowed for repair is 15 minutes.

### **SERVICE ACTION:**

Remove the "EXIT" label from the affected window and install black shrink wrap over the red handle.

encl. - Owners Letter

#### **Mark Owens**

Director of Service and Warranty Administration