

Part 573 Safety Recall Report

19V-406

Manufacturer Name : Jayco, Inc.

Submission Date : MAY 30, 2019

NHTSA Recall No. : 19V-406

Manufacturer Recall No. : na



Manufacturer Information :

Manufacturer Name : Jayco, Inc.

Address : 903 South Main Street

PO Box 460 Middlebury IN 46540

Company phone : 800-283-8267

Population :

Number of potentially involved : 23

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2020-2020 Jayco Class C Motorhome Greyhawk

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : Spartan provide list of 23 affected chassis sold to Jayco under their recall 19012 - VINS were matched to Jayco product serial numbers to create scope

Production Dates : JAN 07, 2019 - APR 18, 2019

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Description of Noncompliance :

Description of the Noncompliance : Per Spartan, an orifice within the brake relay valve in the brake system may be partially blocked , restricting air flow to the brake chambers . The restriction could reduce the actuation time of the brakes and result in extended stopping distance.

FMVSS 1 : 121 - Air brake systems

FMVSS 2 : NR

Description of the Safety Risk : Increase in stopping distance could occur without warning and increase the risk of a crash

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : Spartan Motors
Address : 1541 Reynolds Rd
Charlotte MICHIGAN 48813
Country : United States

Chronology :

5-16-19 Received email notification from Spartan on upcoming recall 19012. Brake Valve Orifice. Created scope of affected Jayco product by matching chassis VINs provided by Spartan. 5-16-19 Operations notified of upcoming recall and scope to check if any of the affected chassis remain on site and must be repaired by Spartan prior to shipping. 5-29-19 All details of this pass through Chassis recall were presented to our Safety Committee who voted that a recall is required to call out Jayco's products affected by Spartan recall

Description of Remedy :

Description of Remedy Program : Per Spartan, the brake relay valve will be removed and inspected for blockage. If needed, the brake relay valve will be replaced at No Charge by Spartan Service Center.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Current owner of Jayco products will be contacted by Spartan to arrange appointment at Spartan Service Centers for Recall remedy. Spartan will provide parts and labor at no charge to the current owner. Spartan has NOT released the recall as of today 5-30-19,

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported