OMB Control No.: 2127-0004

Part 573 Safety Recall Report

19V-413

Manufacturer Name: Life Line Emergency Vehicles

Submission Date: JUN 05, 2019 NHTSA Recall No.: 19V-413 Manufacturer Recall No.: NR



Manufacturer Information:

Manufacturer Name: Life Line Emergency Vehicles

Address: 1 Life-Line Drive

PO Box 299 Sumner IA 50674

Company phone: 563-578-3317

Population:

Number of potentially involved : 5 Estimated percentage with defect : 100 %

Vehicle Information:

Vehicle 1: 2017-2018 Ford Type 1

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style : 2-DOOR Power Train : DIESEL

Descriptive Information: Monitor image may appear reversed

Production Dates: JAN 01, 2017 - DEC 31, 2018

VIN Range 1 : Begin : NR End : NR Not sequential

Description of Defect:

Description of the Defect: Rear View Mirror Monitor Image may show reversed image.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: The image shown in monitor may be reversed

Description of the Cause: NR
Identification of Any Warning NR
that can Occur:

Supplier Identification:

Component Manufacturer

Name: ASA Electronics Address: 2602 Marina Dr.

Elkhart INDIANA 46514

Country: United States

The information contained in this report was submitted pursuant to 49 CFR §573

Chronolog	v	•
	•	

NR

Description of Remedy:

Description of Remedy Program: ASA will notify owners, and provide repairs, and report on Life Line's

behalf.

How Remedy Component Differs NR

from Recalled Component :

Identify How/When Recall Condition NR

was Corrected in Production:

Recall Schedule:

Description of Recall Schedule: NR

Planned Dealer Notification Date : NR - NR Planned Owner Notification Date : NR - NR

* NR - Not Reported