

Recall Quarterly Report

19V-437

Manufacturer Name : Lakota Corporation
NHTSA Recall No. / MFR Recall No. : 19V-437 /
Recall Subject : Aluminum Axle Carrier may Tear
Owner Notification Beginning Date : JUL 25, 2019
Owner Notification End Date:



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	OCT 23, 2019	2019-3	371	186	0	3

This Document Last Updated : OCT 23, 2019

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).
Recall Population : The total number of products recalled by the manufacturer.
Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.
Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.
Total Removed : Products that have been scrapped, stolen, or exported.