

# Part 573 Safety Recall Report

# 19V-439

**Manufacturer Name :** LA WEST INC**Submission Date :** JUN 11, 2019**NHTSA Recall No. :** 19V-439**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : LA WEST INC

Address : 196 CRAWFORD RD  
STATESVILLE NC 28625

Company phone : 7044984940

**Population :**

Number of potentially involved : 15

Estimated percentage with defect : 95 %

**Vehicle Information :**

Vehicle 1 : 2018-2019 Ford Transit

Vehicle Type : BUSES, MEDIUM &amp; HEAVY VEHICLES

Body Style : VAN

Power Train : GAS

Descriptive Information : LA West reviewed all purchases made to SMI for said hatch during the time frame provided by the Recall Notice from SMI.

Production Dates : AUG 01, 2018 - APR 01, 2019

VIN Range 1 : Begin : NR End : NR

 Not sequential**Description of Defect :**

Description of the Defect : SMI has determined that some Transpec Glass Hatches may contain edge defects (chips) in the glass panels that have resulted from the manufacturing process

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Hot/cold and vibration/shock can create stress concentrations at these edge defects that may result in fracture and failure of the tempered glass if edge damage is present

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

**Supplier Identification :**

**Component Manufacturer**

Name : Specialty Manufacturing, Inc  
Address : 13501 S Ridge Dr  
Charlotte NORTH CAROLINA 28273  
Country : United States

**Chronology :**

NR

**Description of Remedy :**

Description of Remedy Program : Transpec glass hatch replacement kits will be sent to you upon request and will include complete instructions on the removal and re-installation of the defective components. Removal and re-installation of each Transpec glass hatch lid can be accomplished in 15 minutes, for which SMI will reimburse installers \$30.00 for each remedied hatch.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : Upon receiving notification from SMI, all remaining inventory at LA West was quarantined and inspected.

**Recall Schedule :**

Description of Recall Schedule : Will send out a letter to all the dealers effected by this recall, as well as notify by written letter all owners if vehicles have been sold

Planned Dealer Notification Date : JUN 17, 2019 - AUG 17, 2019

Planned Owner Notification Date : JUN 17, 2019 - AUG 17, 2019

\* NR - Not Reported