Recall Quarterly Report

19V-484

Manufacturer Name : Oshkosh Corporation NHTSA Recall No. / MFR Recall No. : 19V-484 / Recall Subject : Hydraulic Tank Overpressurize and Rupture Owner Notification Beginning Date : AUG 09, 2019 Owner Notification End Date: AUG 09, 2019



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	OCT 25, 2019	2019-3	94	13	0	0

This Document Last Updated : OCT 25, 2019

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012). Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory. Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.