OMB Control No.: 2127-0004

Recall Quarterly Report

19V-569

Manufacturer Name: Honda (American Honda Motor Co.)

NHTSA Recall No. / MFR Recall No. : 19V-569 /A5I

Recall Subject: Fuel Tank Joint Weld May Fail

Owner Notification Beginning Date : SEP 16, 2019

Owner Notification End Date: SEP 16, 2019



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
3	APR 16, 2020	2020-1	134	122	0	0
2	JAN 13, 2020	2019-4	134	113	1	0
1	OCT 25, 2019	2019-3	134	75	3	0

This Document Last Updated: APR 17, 2020

Definitions:

Report Quarter: The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3^{rd} quarter of 2012). Recall Population: The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.