

Recall Quarterly Report

19V-727

Manufacturer Name : Forest River, Inc.

NHTSA Recall No. / MFR Recall No. : 19V-727 / 53-1100

Recall Subject : Axle may Contact Chassis

Owner Notification Beginning Date : NOV 01, 2019

Owner Notification End Date: NOV 04, 2019



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	JAN 17, 2020	2019-4	44	7	0	0

This Document Last Updated : JAN 17, 2020

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.