

## MAZDA DEALER EMAIL

January 21, 2020


Attention: Mazda General, Parts and Service Managers

Subject: Notification of Safety Recall 4219L – 2019 - 2020MY Mazda3 Sudden Deceleration from False Brake Activation – REPAIR VIN CALCULATOR

## Concern Outline:

Certain subject vehicles may unexpectedly stop while driving due to inadvertent activation of the Smart Brake Support (SBS), which is an automatic emergency braking system, increasing the risk of a rear-end crash from a following vehicle.

There are three different repairs for this recall depending on the VIN range, Repair "A", "B" or "C". We have created a Recall 4219L VIN Look Up Tool Job Aid - VIN Repair Calculator and posted to MGSS that will allow the dealer to look up which repair to perform. If you do not have Excel (or a similar spreadsheet program installed) you may receive an error when opening this document.



The VIN Look Up Tool is a macro-enabled Excel document. You may receive a warning to enable macros in order to use this Look Up Tool. Please click on "Enable Content" and agree that this is a trusted document.



As a reminder, all vehicles under this recall will show as "Not Launched" status in eMDCS. The vehicle can be delivered once the recall repair has been completed. Dealers must complete all affected in-stock inventory as quickly as possible. Be sure to read the updated repair instructions to minimize any potential module issues.

For customers that arrive at your dealership or inquire about this recall and demands a repair prior to launch, dealers must perform the repair.

## **Owner Notification:**

Mazda will notify owners of affected vehicles by first class mail no later than February 17, 2020. Owners will be asked to bring their vehicle to the nearest Mazda dealership for repairs.

## **Protect What is Important to You**

Mazda North American Operations

Sincerely,

Travis Young Manager Recalls, Technical Services Division Mazda North American Operations

MAZDA NORTH AMERICAN OPERATIONS