

## IMPORTANT SAFETY RECALL NHTSA Recall No. 20E-021

April 17, 2020

Blue Gas Marine, Inc. Attn: Andrew Priest 2528 Schieffelin Road Apex, NC 27502

Subject: Incorrect Label for 327L Type 3 Cylinder

Dear Andrew Priest:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. WFT has determined that the label on the 327L Type 3 Cylinder do not conform to Federal Motor Vehicle Safety Standards (FMVSS) No. 304 "Compressed Natural Gas Fuel Container Integrity."

## WHY IS A RECALL BEING CONDUCTED?

The label font size on the 327L type 3 cylinders (part# CNG-327L-2560N) is too small and missing the type 3-cylinder designation, which can cause them to fail inspection. If the cylinders are unable to pass inspection, it can increase the risk of a fire or injury.

## WHAT ARE WE DOING?

WFT has included 3 replacement compliant labels. We ask that you install them over the top of the existing cylinder labels. Please use an epoxy sealer to seal the edges of the label over the top of the old label. This repair will take approximately 10 minutes after the epoxy sealer is prepared.

## WHO SHOULD YOU CONTACT IF YOU HAVE FURTHER QUESTIONS OR CONCERNS?

If you have any questions or concerns about this recall, please contact Michael Gross at 334-758-8530. If you have a complaint related to this recall, you may report it to the following:

Administrator National Highway Traffic Safety Administration 1200 New Jersey Avenue, SE Washington, DC 20590

You may also call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <u>http://www.safercar.gov</u>.

Sincerely,

Michael Gross WFT Quality & Logistics Manager