

# Part 573 Safety Recall Report

## 20E-082

**Manufacturer Name :** Leather on wheels Inc**Submission Date :** OCT 27, 2020**NHTSA Recall No. :** 20E-082**Manufacturer Recall No. :** NR**Manufacturer Information :****Population :**

Manufacturer Name : Leather on wheels Inc

Number of potentially involved : 4,896

Address : 321 5000 canoe pass way  
Delta 00 V4m0b3

Estimated percentage with defect : 100 %

Company phone : 5875830070

**Equipment Information :**

Brand / Trade 1 : WCL Helmet

Model : Polo, 666

Part No. : 666

Size : XXS-XXL

Function : NR

Descriptive Information : The entire population has been included for this model of helmets. that were imported by us.

Production Dates : SEP 01, 2014 - MAR 16, 2020

**Description of Defect :**

Description of the Defect : Entire population of these helmets has been found to be in non compliance of the FMVSS 218 due to labelling and protection issues. The helmet may not protect the user appropriately.

FMVSS 1 : 218 - Motorcycle helmets

FMVSS 2 : NR

Description of the Safety Risk : the helmet may not protect the user appropriately.

Description of the Cause : Non Compliance has occurred due to several reasons. The labeling on the helmet is not in compliance. Additionally the helmet may not protect the user adequately in case of a crash. The cause is an inferior mold and materials used,

Identification of Any Warning NA  
that can Occur :**Involved Components :**

Component Name : NR

Component Description : NR

Component Part Number : NR

Component Name : NR

Component Description : NR

Component Part Number : NR

### Supplier Identification :

#### Component Manufacturer

Name : Wenzhou Leiden helmet MFG co LTd

Address : no 220 yonging two road ,  
yueqing chengdong industrial zone yeuqing FOREIGN STATES

Country : China

### Chronology :

The department of transportation tested these helmets and found that these were in non compliance so we have decided to recall these items.

### Description of Remedy :

Description of Remedy Program : Return helmet for credit or a replacement helmet that is in compliance.

How Remedy Component Differs from Recalled Component : These models will be produced by a different factory with better materials and craftsmanship.

Identify How/When Recall Condition was Corrected in Production : We are going to switch to a different manufacturer and any models that we import will have to be tested and the test results provided will be verified to ensure that every helmet is in compliance.

### Recall Schedule :

Description of Recall Schedule : We will try to reach all dealers and consumers of this product as soon as possible and inform them of the defect.

Planned Dealer Notification Date : NOV 20, 2020 - DEC 20, 2020

Planned Owner Notification Date : NOV 20, 2020 - DEC 20, 2020

**Purchaser Information :**

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name : NR

Address : NR

NR

Country : NR

Company Phone : NR

\* NR - Not Reported