

Part 573 Safety Recall Report

20V-023

Manufacturer Name : Terex Advance Mixer, Inc.**Submission Date :** JAN 17, 2020**NHTSA Recall No. :** 20V-023**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Terex Advance Mixer, Inc.

Address : 7727 Freedom Way

Fort Wayne IN 46818

Company phone : 999

Population :

Number of potentially involved : 12

Estimated percentage with defect : NR

Vehicle Information :

Vehicle 1 : 2020-2020 Terex Advance Mixer FDC300, FD4000, FD5000GL, FD7000B

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : Dana provided Terex Advance Mixer with axle serial numbers that might have a quality issue. Dana also provided direction for how to inspect the axles to determine if they were part of this quality issue. From the axle serial numbers Terex Advance Mixer was able to determine what chassis VIN numbers needed to be inspected for this defect.

Production Dates : DEC 16, 2019 - JAN 07, 2020

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Defect :**

Description of the Defect : Awaiting formal write up from Dana in order to properly describe the defect.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : To be filled in

Description of the Cause : NR

Identification of Any Warning NR
that can Occur :

Supplier Identification :**Component Manufacturer**

Name : Dana
Address : NR
NR
Country : United States

Chronology :

NR

Description of Remedy :

Description of Remedy Program : NR
How Remedy Component Differs NR
from Recalled Component :
Identify How/When Recall Condition NR
was Corrected in Production :

Recall Schedule :

Description of Recall Schedule : NR
Planned Dealer Notification Date : NR - NR
Planned Owner Notification Date : NR - NR

* NR - Not Reported