IMPORTANT SAFETY RECALL

KZ RV, L.P.

NHTSA Recall Number 20V-Transport Canada Recall Number 2020-

Date: Click here to enter a date.

TO: KZ RV Dealer

Problem

The vehicles subject to this recall were built with propane lines that are too close to the tire. The lines could become damaged by debris which results in a gas leak that could result in a fire or explosion resulting in personal injury or death.

RANGE OF VEHICLES INVOLVED:

2020 Connect SE models C271RLSE and C312BHKSE

WARRANTY REIMBURSEMENT:

A notice of this recall has been sent to affected retail owners. A copy of the Owner's letter is included for your review. They may request that you complete the repair. If so, please follow the warranty reimbursement procedure. If the unit and/or units are in your inventory, or if you are requested to perform the repair for the retail customer, please complete the advised repair and send in a warranty claim referencing this recall number for reimbursement. The time allowed for repair is 1 hour.

SERVICE ACTION:

Reroute the propane lines away from the path of the tire.

encl. - Owners Letter

Delbert Miller

Vice President Corporate