OMB Control No.: 2127-0004

Part 573 Safety Recall Report

20V-059

Manufacturer Name: Vac-Tron Equipment, LLC

Submission Date: FEB 28, 2020 NHTSA Recall No.: 20V-059 **Manufacturer Recall No.:** VVK0004



Manufacturer Information:

Manufacturer Name: Vac-Tron Equipment, LLC

Address: 27137 South Hwy 33

Okahumpka FL 34762

Company phone: 728-2222

Population:

Number of potentially involved: 2,223 Estimated percentage with defect: 99 %

Vehicle Information:

Vehicle 1: 2019-2020 Vac-Tron LPSDT

Vehicle Type: TRAILERS

Body Style : Power Train : NR

Descriptive Information: The recall population was determined by reviewing current and recent models

regarding marking and lighting regulations and the discovery of those reviews. The units not included in the recall did not have the same lighting and marking as these

models.

2,243 total units

Production Dates: FEB 01, 2019 - FEB 15, 2020

VIN Range 1: Begin: 5HZG16213KK002001 End: 5HZG16215LK002261 Not sequential

Vehicle 2: 2017-2018 Vac-Tron AIR373SDT

Vehicle Type: TRAILERS

Body Style : Power Train : NR

Descriptive Information: The recall population was determined by reviewing current and recent models

regarding marking and lighting regulations and the discovery of those reviews. The units not included in the recall did not have the same lighting and marking as these

models.

2.234 total trailers

Production Dates: JUL 10, 2017 - SEP 24, 2018

VIN Range 1: Begin: 5HZBF1626HLGH1284 End: 5HZBF2429JLJJ5101 ✓ Not sequential

Vehicle 3: 2018-2018 Vac-Tron AIR555SDT

Vehicle Type: TRAILERS

Body Style:

Power Train :	
Descriptive Information :	The recall population was determined by reviewing current and recent models regarding marking and lighting regulations and the discovery of those reviews. The units not included in the recall did not have the same lighting and marking as these models.
	2,234 total trailers
Production Dates :	APR 29, 2018 - APR 29, 2018
VIN Range 1:	Begin: 5HZBF1625CLDC1251 End: 5HZBF1625CLDC1251
Vehicle 4:	2016-2018 Vac-Tron AIR573SDT
Vehicle Type :	TRAILERS
Body Style :	
Power Train :	
Descriptive Information :	The recall population was determined by reviewing current and recent models regarding marking and lighting regulations and the discovery of those reviews. The units not included in the recall did not have the same lighting and marking as these models.
	2,234 total trailers
Production Dates :	JAN 01, 2016 - OCT 01, 2018
VIN Range 1:	Begin: 5HZBF1623GLAG1101 End: 5HZBF1627JLKJ1493 ✓ Not sequential
Vehicle 5 : Vehicle Type :	2018-2018 Vac-Tron AIR573XDT
Body Style :	
Power Train:	NR
Descriptive Information :	The recall population was determined by reviewing current and recent models regarding marking and lighting regulations and the discovery of those reviews. The
	units not included in the recall did not have the same lighting and marking as these models.
	2,234 total trailers
Production Dates :	MAR 10, 2018 - MAR 10, 2018
VIN Range 1:	Begin: 5HZBF1625JLCJ1172 End: 5HZBF1625JLCJ1172
Vehicle 6:	2016-2018 Vac-Tron AIR873SDT
Vehicle Type :	TRAILERS
Body Style :	
Power Train:	
Descriptive Information :	The recall population was determined by reviewing current and recent models regarding marking and lighting regulations and the discovery of those reviews. The units not included in the recall did not have the same lighting and marking as these

models.
2,234 total trailers
Production Dates: AUG 01, 2016 - OCT 15, 2018 VIN Range 1: Begin: 5HZBF192XGLHG2164 End: 5HZBF1923JLKJ2328 ✓ Not sequential
Vehicle 7: 2019-2020 Vac-Tron AIRSDT Vehicle Type: TRAILERS Body Style: Power Train: NR
Descriptive Information: The recall population was determined by reviewing current and recent models regarding marking and lighting regulations and the discovery of those reviews. The units not included in the recall did not have the same lighting and marking as these models.
2,234 total trailers
Production Dates: MAR 01, 2019 - JAN 01, 2020 VIN Range 1: Begin: 5HZA192VXKK002006 End: 5HZA162V5LK002026
Vehicle 8: 2017-2018 Vac-Tron CV570GT Vehicle Type: TRAILERS Body Style:
Power Train: NR Descriptive Information: The recall population was determined by reviewing current and recent models regarding marking and lighting regulations and the discovery of those reviews. The units not included in the recall did not have the same lighting and marking as these models.
2,234 total trailers
Production Dates : AUG 07, 2017 - APR 11, 2018 VIN Range 1 : Begin : 5HZBF1626HLHH1319 End : 5HZBF1622HLJH1393 ☑ Not sequential VIN Range 2 : Begin : 5HZBF1623JLCJ1199 End : 5HZBF1622JLDJ1228 ☑ Not sequential
Vehicle 9: 2017-2018 Vac-Tron CV570SGT Vehicle Type: TRAILERS Body Style: Power Train: NR
Descriptive Information : The recall population was determined by reviewing current and recent models regarding marking and lighting regulations and the discovery of those reviews. The units not included in the recall did not have the same lighting and marking as these models.

2	2,234 total trailers		
Production Dates : M	MAY 21, 2017 - MAR 08, 2018		
	egin: 5HZBF1623HLEH1219	End: 5HZBF1623HLEH1219	■ Not sequential
VIN Range 2: Be		End: 5HZBF1628JLCJ1196	☐ Not sequential
	2016-2019 Vac-Tron CV573GT		
Vehicle Type: T	RAILERS		
Body Style : Power Train : N	VID.		
		mined by reviewing current and a	rocant modals
r u	regarding marking and lighting	mined by reviewing current and a regulations and the discovery of the lid not have the same lighting and	those reviews. The
2	2,234 total trailers		
Production Dates: S	SEP 01, 2016 - DEC 18, 2018		
· ·	egin: 5HZBF1629GLJG1250		✓ Not sequential
VIN Range 2: Be	egin: 5HZBF1629KLMJ1535	End: 5HZBF1622KLMJ1554	☐ Not sequential
Vehicle 11: 2 Vehicle Type: T	2016-2019 Vac-Tron CV573SGT		
Body Style :			
Power Train: N	JR		
r u	regarding marking and lighting	mined by reviewing current and regulations and the discovery of the lid not have the same lighting and	those reviews. The
2	2,234 total trailers		
Production Dates: 0	OCT 01, 2016 - JAN 01, 2019		
VIN Range 1: Be		End: 5HZBF1624HLLH1465	✓ Not sequential
VIN Range 2: Be		End: 5HZBF1620JLMJ1518	☐ Not sequential
VIN Range 3: Be		End: 5HZBF1624KLLJ1570	☐ Not sequential
VIN Range 4:Be	egin: 5HZBF1625KLAK1101	End: 5HZBF1620KLAK1149	☐ Not sequential
Vehicle 12: 2	2016-2018 Vac-Tron CV870GT		
Vehicle Type: T	TRAILERS		
Body Style :			
Power Train: N			
r	regarding marking and lighting	mined by reviewing current and negulations and the discovery of the lid not have the same lighting and	those reviews. The

models.
2,234 total trailers
Production Dates: NOV 04, 2017 - SEP 14, 2018
VIN Range 1: Begin: 5HZBF162XHLLH1471 End: 5HZBF162XHLLH1471 Not sequential
VIN Range 2: Begin: 5HZBF162XJLMH1110 End: 5HZBF1929JLJJ2296 Not sequential
The sequences
Vehicle 13: 2017-2019 Vac-Tron CV870SGT
Vehicle Type: TRAILERS
Body Style:
Power Train: NR
Descriptive Information : The recall population was determined by reviewing current and recent models regarding marking and lighting regulations and the discovery of those reviews. The units not included in the recall did not have the same lighting and marking as these models.
2,234 total trailers
Production Dates: SEP 05, 2017 - JAN 11, 2019
VIN Range 1: Begin: 5HZBF1626HLJH1395 End: 5HZBF1926KLAK2138 Vin Sequential
0. 10.
Vehicle 14: 2016-2019 Vac-Tron CV873GT
Vehicle Type: TRAILERS
Body Style :
Power Train: NR
Descriptive Information : The recall population was determined by reviewing current and recent models regarding marking and lighting regulations and the discovery of those reviews. The units not included in the recall did not have the same lighting and marking as these models.
2,234 total trailers
Production Dates: SEP 01, 2016 - DEC 01, 2018
VIN Range 1 : Begin : 5HZBF1622GLJG1249 End : 5HZBF192XKLMJ2365 ✓ Not sequential
Vehicle 15: 2017-2019 Vac-Tron CV873SGT
Vehicle Type: TRAILERS
Body Style:
Power Train: NR
Descriptive Information: The recall population was determined by reviewing current and recent models regarding marking and lighting regulations and the discovery of those reviews. The units not included in the recall did not have the same lighting and marking as these models.

	2,234 total trailers
Production Dates :	FEB 06, 2017 - FEB 01, 2019
	Begin: 5HZBF1628HLBH1143 End: 5HZBF1922KLBK2141 ✓ Not sequential
Vehicle 16:	2019-2020 Vac-Tron CVGT
Vehicle Type :	TRAILERS
Body Style :	
Power Train :	NR
Descriptive Information :	The recall population was determined by reviewing current and recent models regarding marking and lighting regulations and the discovery of those reviews. The units not included in the recall did not have the same lighting and marking as these models.
	2,234 total trailers
Production Dates :	FEB 01, 2019 - MAR 15, 2020
	Begin: 5HZC162XXKK002001 End: 5HZC162X9LK002122 Not sequential
	2019-2020 Vac-Tron CVSGT
Vehicle Type :	
Body Style :	
Power Train :	
Descriptive Information :	The recall population was determined by reviewing current and recent models regarding marking and lighting regulations and the discovery of those reviews. The units not included in the recall did not have the same lighting and marking as these models.
	2,234 total trailers
Production Dates :	FEB 01, 2019 - MAR 15, 2020
VIN Range 1:	Begin: 5HZD192Y1KK002001 End: 5HZD192Y8LK002143 Not sequential
	2017-2017 Vac-Tron LP533SDT
Vehicle Type :	
Body Style :	
Power Train :	
Descriptive Information :	The recall population was determined by reviewing current and recent models regarding marking and lighting regulations and the discovery of those reviews. The units not included in the recall did not have the same lighting and marking as these models.
	2,234 total trailers
Production Dates :	APR 11, 2017 - APR 11, 2017
	Begin: 5HZBF1628HLDH1200 End: 5HZBF1628HLDH1200 Not sequential

Vehicle 19:	2016-2019 Vac-Tron LP573SDT
Vehicle Type :	TRAILERS
Body Style :	
Power Train:	NR
Descriptive Information :	The recall population was determined by reviewing current and recent models regarding marking and lighting regulations and the discovery of those reviews. The units not included in the recall did not have the same lighting and marking as these models.
	2,234 total trailers
Production Dates:	JAN 01, 2016 - JAN 15, 2019
	Begin: 5HZBF1627GLAG1103 End: 5HZBF1623KLAK1579 ✓ Not sequential
viiv kange 1.	begiii. 3112DF1027GLAG1103 Elid. 3112DF1023KLAK1373 V Not sequential
Vehicle 20:	2016-2019 Vac-Tron LP573SGT
Vehicle Type :	
Body Style :	
Power Train :	NR
Descriptive Information :	The recall population was determined by reviewing current and recent models
•	regarding marking and lighting regulations and the discovery of those reviews. The units not included in the recall did not have the same lighting and marking as these models.
	2,234 total trailers
Draduation Dates	IAN 01 2016 IAN 01 2010
	JAN 01, 2016 - JAN 01, 2019 Pagin - 51/7PE1621CI AC1100 End - 51/7PE1626H VI1470
C .	Begin: 5HZBF1621GLAG1100 End: 5HZBF1626JLKJ1470 ✓ Not sequential Begin: 5HZBF1627KLMJ1551 End: 5HZBF1628KLLJ1555 ✓ Not sequential
· ·	
· ·	
_	Begin: 5HZBF1628KLAK1111 End: 5HZBF1628KLAK1111 Not sequential Begin: 5HZBF1628KLAK1111 End: 5HZBF1628KLAK1111 Not sequential
viiv kange 5.	Begin: 5HZBF1628KLAK1111 End: 5HZBF1628KLAK1111 Not sequential
Vehicle 21:	2016-2019 Vac-Tron LP573XDT
Vehicle Type :	
Body Style :	
Power Train :	
	The recall population was determined by reviewing current and recent models
2 0001-per (0 222-0222-0222-022-022-022-022-022-022	regarding marking and lighting regulations and the discovery of those reviews. The
	units not included in the recall did not have the same lighting and marking as these
	models.
	2,234 total trailers
Don't C. D.	IAN 01 0010 DEC 01 0010
	JAN 01, 2016 - DEC 01, 2018 Paris 51/7PE1095CLAC1109 Feel 51/7PE1090VLM1579
VIN Kange 1:	Begin: 5HZBF1625GLAG1102 End: 5HZBF1626KLMJ1573 ✓ Not sequential

Vehicle 22:	2016-2016 Vac-Tron LP800SGT
Vehicle Type :	TRAILERS
Body Style :	
Power Train:	NR
Descriptive Information :	The recall population was determined by reviewing current and recent models
	regarding marking and lighting regulations and the discovery of those reviews. The units not included in the recall did not have the same lighting and marking as these
	models.
	2,234 total trailers
Production Dates :	JUN 01, 2016 -JUN 01, 2016
VIN Range 1:	Begin: 5HZBF1921GLFG2144 End: 5HZBF1921GLFG2144 ✓ Not sequential
Walish on	2016-2019 Vac-Tron LP873SDT
Vehicle Type :	
Body Style:	IRAILERS
Power Train :	NR
	The recall population was determined by reviewing current and recent models
Descriptive information.	regarding marking and lighting regulations and the discovery of those reviews. The
	units not included in the recall did not have the same lighting and marking as these
	models.
	2,234 total trailers
Production Dates:	JAN 01, 2016 - FEB 08, 2019
	Begin: 5HZBF1921GLAG2100 End: 5HZBF1924KLBK2142 Not sequential
	208 01
Vehicle 24:	2016-2019 Vac-Tron LP873SGT
Vehicle Type :	TRAILERS
Body Style :	
Power Train :	NR
Descriptive Information :	The recall population was determined by reviewing current and recent models
	regarding marking and lighting regulations and the discovery of those reviews. The units not included in the recall did not have the same lighting and marking as these
	models.
	2,234 total trailers
Production Dates :	FEB 05, 2016 - JAN 01, 2019
	Begin: 5HZBF1922GLBG2108 End: 5HZBF1920JLMJ2342 ✓ Not sequential
VIN Range 2:	Begin: 5HZBF1929KLAK2120 End: 5HZBF1929KLAK2120 Not sequential
V.1+1 05	9010 9010 V T I D070VDT
	2016-2019 Vac-Tron LP873XDT
Vehicle Type :	INAILERS

Body Style : Power Train :	
Descriptive Information :	The recall population was determined by reviewing current and recent models regarding marking and lighting regulations and the discovery of those reviews. The units not included in the recall did not have the same lighting and marking as these models.
	2,234 total trailers
	JAN 15, 2016 - JAN 02, 2019 Begin: 5HZBF1929GLAG2104 End: 5HZBF192XKLAK2143 ✓ Not sequential
Vehicle 26 : Vehicle Type : Body Style : Power Train :	
	The recall population was determined by reviewing current and recent models regarding marking and lighting regulations and the discovery of those reviews. The units not included in the recall did not have the same lighting and marking as these models. 2,234 total trailers
Production Dates :	FEB 01, 2019 - MAR 15, 2020
	Begin: 5HZH16227KK002001 End: 5HZH19227LK002048 ☐ Not sequential
Vehicle 27 : Vehicle Type : Body Style : Power Train :	
Descriptive Information :	The recall population was determined by reviewing current and recent models regarding marking and lighting regulations and the discovery of those reviews. The units not included in the recall did not have the same lighting and marking as these models.
	2,234 total trailers
Production Dates : VIN Range 1 :	FEB 01, 2019 - MAR 15, 2020 Begin: 5HZJ16234KK002001 End: 5HZJ19234LK002163 ☐ Not sequential

Description of Noncompliance:

Description of the 1. No front side marker lamps.

Noncompliance: 2. No front width clearance lamps.

3. Conspicuity tape does not meet length requirements of the side of the

trailer.

4. No front side reflex reflectors.

5. No rear upper body marking.

6. No rear side marker lamps.

7. No rear side reflex reflectors.

8. No rear reflex reflectors placed at trailers widest point.

FMVSS 1: 108 - Lamps, reflective devices, and assoc. Equipment

FMVSS 2: NR

Description of the Safety Risk: When towing or parking the vacuum excavator on public roadways, a crash

may occur resulting in death or serious injury resulting from a driver(s) of other vehicle(s) not seeing the vacuum excavator at night or during limited sunlight and strike the vacuum excavator. To reduce the potential of this occurring, vehicle lights will be relocated, additional reflectors and

conspicuity tape are being added. Property or equipment damage may also

occur.

Description of the Cause: NR

Identification of Any Warning NR

that can Occur:

Supplier Identification:

Component Manufacturer

Name: NR

Address: NR

NR

Country: NR

Chronology:

1/10/2020 Engineering researching current production of low chassis trailers with engineering drawings. 1/21/2020 Meeting with Production and Engineering on research for lighting and marking on production trailers.

1/27/2020 Declaration of noncompliance of 49CFR 507.108

1/31/2020 Report to NHTSA and Transport Canada

Description of Remedy:

Description of Remedy Program: Vac-Tron will send necessary parts and instructions to resolve

noncompliance issues. Dealers will be reimbursed for their parts and

labor.

How Remedy Component Differs Addition of conspicuity tape that was not installed originally on the sides from Recalled Component: of the machine. Addition of reflectors that were not installed originally, Movement of the Marker lights from noncompliant position to compliant position. Install conspicuity tape, and reflectors that were not installed on

rear of the original machine.

Identify How/When Recall Condition All machines on the production line will be changed thru ECN's to add the

was Corrected in Production: correct lighting, conspicuity tape, and reflectors. This will begin

3-30-2020.

Recall Schedule:

Description of Recall Schedule: Dealer notification will be sent 03/17/2020 by email with list of affected

machines in their area of responsibility. Owner notification letters will be sent 03/31/2020 with translated letters were necessary for their affected

Planned Owner Notification Date: MAR 31, 2020 - MAR 31, 2020

Planned Dealer Notification Date: MAR 17, 2020 - MAR 17, 2020

* NR - Not Reported