OMB Control No.: 2127-0004

Part 573 Safety Recall Report

20V-235

Manufacturer Name: Blue Bird Body Company

Submission Date: APR 27, 2020 **NHTSA Recall No.:** 20V-235 **Manufacturer Recall No.:** R20AO-NSB



Manufacturer Information:

Manufacturer Name: Blue Bird Body Company

Address: P.O. Box 937

402 Blue Bird Boulevard Fort Valley

GA 31030

Company phone: 478-822-2242

Population:

Number of potentially involved : 3 Estimated percentage with defect : 100%

Vehicle Information:

Vehicle 1: 2009-2019 Blue Bird Vision

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER Power Train : GAS

Descriptive Information: It has been determined that certain Blue Bird buses could fail to conform to the

Federal Motor Vehicle Safety Standard No. 105 "Hydraulic and Electric Brake Systems" requirements for the parking brake system requirements. Subject buses

may fail to meet the FMVSS 105 S5.2.3 requirements for holding the vehicle

stationary for 5 minutes on a 20% grade when loaded to its maximum gross vehicle weight. The potentially suspect population includes buses equipped with hydraulic brakes with a hand lever mounted on the right side of the driver seat to actuate the parking brake (feature 40049-03). Blue Bird shall conduct a voluntary safety recall to correct any potential noncompliance. Blue Bird has evaluated the risk to motor vehicle safety related to this noncompliance and determined that there is a potential for injury to the occupant and bystanders in the event that the parking brake system is set to an insufficient application force.

Production Dates: SEP 06, 2008 - MAR 12, 2018

Description of Defect:

Description of the Defect: It has been determined that certain Blue Bird buses could fail to conform to the Federal Motor Vehicle Safety Standard No. 105 "Hydraulic and Electric Brake Systems" requirements for the parking brake system requirements. Subject buses may fail to meet the FMVSS 105 S5.2.3 requirements for holding the vehicle stationary for 5 minutes on a 20% grade when loaded to its maximum gross vehicle weight. The potentially suspect population includes buses equipped with hydraulic brakes with a hand lever mounted on the right side of the driver seat to actuate the parking brake (feature 40049-03). Blue Bird shall conduct a voluntary safety recall to correct any potential noncompliance. Blue Bird has evaluated the risk to motor vehicle safety related to this noncompliance and determined that there is a potential for injury to the occupant and bystanders in the event that the parking brake system is set to an insufficient application force.

FMVSS 1: 105 - Hydraulic and electric brake systems

FMVSS 2: NR

Description of the Safety Risk: There is an increase possibility of unintended movement when the vehicle is parked in the event that the parking brake system is set to an insufficient application force. Should the vehicle experience the unintended movement when the vehicle is parked then there is a potential for injury to the occupant and bystanders.

Description of the Cause: Blue Bird determined that manufacturing variation may have resulted in a lower application force than intended for unit equipped with hydraulic brakes and a right-hand floor mounted hand lever park brake. Additionally, Blue Bird determined that the hand lever application force may not be checked in accordance with the service manual recommendations. The inspection interval presented in the service manual for the hand brake lever application force is every month or 3,000 miles. For these reasons, Blue Bird is conducting a voluntary safety recall to correct any potential FMVSS 105 noncompliance when loaded to the maximum gross vehicle weight on a 20% grade.

that can Occur:

Identification of Any Warning There is no audible or visual warning, which would precede an event.

Involved Components:

Component Name 1: NR

Component Description: NR Component Part Number: NR

Supplier Identification:

Component Manufacturer

Name: NR

Address: NR

NR

Country: NR

Chronology:

On October 28, 2019, a Blue Bird Field Service representative reviewed a bus that experienced a rollback event with the parking brake engaged. This bus is equipped with hydraulic brakes with a right-hand floor mounted hand lever park brake lever. Upon inspection, it was determined that the hand lever application force was under the requirements, as stated in service manual. The inspection interval presented in the service manual for the hand brake lever application force is every month or 3,000 miles. On November 11, 2019, Blue Bird confirmed that neither the Dealer nor Owner had completed the application force inspection on the bus in question nor the other buses with the same parking brake configuration. In December 2019, Blue Bird surveyed other dealers with buses equipped with the same parking brake configuration and determined that this inspection requirement has a very low accomplishment rate. In January 2020, Blue Bird confirmed that the in-process certification inspection of the hand parking brake lever application force was being performed on every unit. In February 2020, Blue Bird completed an internal audit on the original hand parking brake lever application force inspection point and determined that manufacturing variation may have resulted in a lower application force than intended. In April 2020, Blue Bird determined that buses equipped with hydraulic brakes with a right-hand floor mounted hand park brake lever and a delivery date before March, 2020, should be recalled to confirm that the application force is set to the requirement.

Description of Remedy:

Description of Remedy Program: Blue Bird will notify the affected dealers and owners that the application

force of the floor mounted park brake hand lever assembly must be

inspected and set according to the Blue Bird Service Manual requirements,

if found to be incorrect.

How Remedy Component Differs NR

from Recalled Component:

Identify How/When Recall Condition NR

was Corrected in Production:

Recall Schedule:

Description of Recall Schedule: No Parts are required for this campaign. Dealer and Owner Notification to

be issued on or before June 24, 2020.

Planned Dealer Notification Date: JUN 24, 2020 - JUN 24. 2020

Part	573	Safety	Recal	l Report
-------------	------------	---------------	-------	----------

20V-235

Page 4

Planned Owner Notification Date : JUN 24, 2020 - JUN 24, 2020

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR \$573