

U.S. Department of Transportation

National Highway Traffic Safety Administration

May 6, 2020

Mr. Greg Gunther Department Manager VCA Mercedes-Benz USA, LLC. 13470 International Parkway Jacksonville, FL 32218 NEF-150JK 20V-246

1200 New Jersey Avenue SE Washington, DC 20590

**Subject:** Water Intrusion into Front Wheel Wells

Dear Mr. Gunther:

This letter serves to acknowledge Mercedes-Benz USA, LLC.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

#### Makes/Models/Model Years:

MERCEDES BENZ/GLB250/2020

Mfr's Report Date: May 1, 2020

NHTSA Campaign Number: 20V-246

**Components:** 

ELECTRICAL SYSTEM STRUCTURE

**Potential Number of Units Affected:** 26

#### **Problem Description:**

Mercedes-Benz USA, LLC. (MBUSA) is recalling certain 2020 GLB 250 vehicles. Water may enter through the wheel well area into the front occupant foot wells, potentially damaging certain electrical components. This may result in the instrument cluster going blank, or an engine stall while driving without the ability to restart the vehicle.

## **Consequence:**

Either a blank instrument cluster display or an engine stall can increase the risk of a crash.

## Remedy:

MBUSA will notify owners, and dealers will seal the vehicle body in the wheel well area and inspect the front foot wells for water intrusion, repairing as necessary, free of charge. The recall is expected to begin June 30, 2020. Owners may contact MBUSA customer service at 1-800-367-6372.

# **Notes:**

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Jennifer Kruger who may be reached by phone at (202) 366-2461, or by email at jennifer.kruger@dot.gov. We look forward to working with you.

Sincerely,

Joshua Neff

Chief, Recall Management Division Office of Defects Investigations

Enforcement

