



**RECREATIONAL
VEHICLES**

985 North 900 West
Shipshewana, IN 46565

IMPORTANT SAFETY RECALL

KZ RV, L.P.

NHTSA Recall Number 20V-296

Transport Canada Recall Number 2020-222

Date: June 1, 2020

TO: KZ RV Dealer

Problem

It has been decided that the vehicles in the recall population fail to conform to the requirements of 49 CFR Part 567 and Part 571.110 in the US and Section 6 and TSD 110 of the MVSR in Canada. The vehicles subject to this recall have been manufactured with the incorrect information on the Federal Identification Tag and Tire Inflation Pressure Label. The labels indicate a Gross Axle Weight Rating (GAWR) of 5,000 lbs., a tire size of ST225/75R15E, a rim size of 15X6J, and a tire inflation pressure of 80 psi. The correct labels should indicate a Gross Axle Weight Rating (GAWR) of 3,500 lbs., a tire size of ST205/75R14D, a rim size of 14X5.5J, and a tire inflation pressure of 65 psi. An incorrect label may lead to unintentionally over inflating the tires, increasing the risk of a crash.

RANGE OF VEHICLES INVOLVED:

- 2018 Escape Models

WARRANTY REIMBURSEMENT:

A notice of this recall has been sent to affected retail owners. A copy of the Owner's letter is included for your review. They may request that you complete the repair. If so, please follow the warranty reimbursement procedure. If the unit and/or units are in your inventory, or if you are requested to perform the repair for the retail customer, please complete the advised repair and send in a warranty claim referencing this recall number for reimbursement. The time allowed for repair is .2 hour.

SERVICE ACTION:

Install the new labels over the existing labels.

encl. – Owners Letter

Delbert Miller

Vice President Corporate