



March, 2021

*** * * IMPORTANT SAFETY RECALL REMINDER * * ***

According to our records, your 2020 Explorer has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number **20S50 - Second row center seat belt buckle bolt not properly secured to seat**
and Description:

What is the issue? On your vehicle, the second row center seat belt buckle may not be properly secured to the seat.

A seat belt buckle that is improperly secured to the seat may not properly restrain an occupant during a crash, increasing the risk of injury.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: owner.ford.com.

Thank you for your attention to this very important matter.

Marzo de, 2021

*** * * RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD * * ***

SegUR nuestros registros, no se realizaron en su 2020 Explorer las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: **20S50 - El perno de la hebilla del cinturón de seguridad central de la segunda fila no está bien asegurado al asiento**

¿Cuál es el problema? En su vehículo, la hebilla del cinturón de seguridad central de la segunda fila podría no estar correctamente fijada al asiento.

Una hebilla de cinturón de seguridad incorrectamente fijada al asiento podría no sujetar de manera adecuada a un ocupante durante un choque, lo cual aumenta el riesgo de sufrir lesiones.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: owner.ford.com.

Gracias por su atención en este asunto sumamente importante.



P.O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID
R K C

A / 0845 / 000000000000030 / A



SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

▶ REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

▶ REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

