## IMPORTANT SAFETY RECALL #2020120005

This notice applies to your vehicle, VIN: 123456 Inspect Fuel Hose and Clamps NHTSA Recall #20V595

Daimler Vans USA, LLC

A Mercedes-Benz AG Company

Robert Veit

Managing Director

Vans USA

December, 2020



- . A remedy is available for your vehicle.
- Schedule an appointment with your authorized Mercedes-Benz dealer as soon as possible.
- This repair will be provided free of charge.

Dear Freightliner Sprinter Owner,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Mercedes-Benz AG ("MBAG"), the manufacturer of Freightliner Sprinter vans, has decided that a defect which relates to motor vehicle safety exists in certain Model Year 2019 Freightliner Sprinter vehicles. Our records indicate that your vehicle is included in the affected population of vehicles.

What is the CONCERN? On certain Sprinter vehicles, the clamps that connect the fuel hose to the fuel line nozzles may not have been properly secured. If the connections are loose or if they loosen over time, fuel could potentially leak. In a worst-case scenario, the fuel hose could completely detach at its connections. Should fuel leak from the loose connection(s), it is possible that fuel could leak onto the cold side of the engine and either evaporate or leak onto the road surface, which could pose a safety hazard to roadway users.

What will your **DEALER DO?** 

An authorized Freightliner dealer will check the fuel hose and its clamp connections and tighten or replace the components as needed. This service will be provided free of charge. While the minimum repair time is approximately 45 minutes, your dealer can provide you with a better estimate of the overall time for this service visit. As a matter of normal service process, an authorized Freightliner dealer will also check for other repair measures which might be applicable to your vehicle and this may increase the required working time. You will not be charged for other service or repairs unless so requested.

Schedule an appointment immediately at your preferred authorized Freightliner Sprinter Dealer. See www.freightlinersprinterusa.com/freightliner/owners-resources/recall for the Dealer Locator. Please mention you are scheduling an appointment to inspect fuel hose and clamps under Recall Campaign # 2020120005. You may be asked for your 17-digit Vehicle Identification Number (VIN) which for your convenience is located above your name at the top of this letter.

We encourage you to sign up for recall alerts at www.nhtsa.gov/alerts. In the event that you are no longer the vehicle owner, or have had a change of address, please complete the reverse side and return the updated information in the enclosed envelope. If this is a leased vehicle and the lessor and registered owner receive this notice, please forward this information by first class mail to the lessee within 10 business days to comply with Federal Regulations.

Should you have any questions difficulty regarding this Recall Campaign, please contact an authorized Freightliner Sprinter dealer. If for any reason a dealer is unable to remedy your situation, we are always happy to hear from you. Please contact us at 1-877-762-8267.

If an authorized Freightliner dealer for any reason is unable to remedy the situation without charge, or within a reasonable amount of time, pursuant to law 49 U.S.C. Chapter 301, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590 or call the toll-free Auto Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153); or go to http://www.safercar.gov.

We apologize for any inconvenience this situation may cause you, but your safety is of utmost concern to Freightliner.

Sincerely,



Daimler Vans USA, LLC One Mercedes-Benz Drive Sandy Springs, GA 30328 Phone (770) 705-0600

<b>IMPORTAN</b>	Τ
-----------------	---

123456

В	for an ELOW esen	, pla	ce ir	ı the	ENC	CLOS	ED E	NVE	LOP	E, ar																			
	☐ EXPORTED ☐ LEASE, VEHICLE RETURNED ☐ SCRAPPED														STOLEN														
	NEW OWNER INFORMATION															MY I	NEW	NAI	ME C	R A	DDR	ESS	IS:						
Las	t Nan	ne, F	irst N	lame	1			1	1		1				ı	ı	1	1					1		1				
Str	Street														1	1	I			I		I	I		Α	pt	1		
City	City														l .		<u> </u>		1		St	ate		ZI	P		<u></u>		
Em	ail Ad	dres	S	ı	ı	1	1	ı	1	1	ı	1	1	1	1	<u>I</u>	1	ı		1	1		ı	<u> </u>	ı		1		
															1														
Pho														Mob	Mobile (numbers only)														

Signature

Date