



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

December 16, 2020

Mr. Jerry Mccarthy
Grand Design RV, LLC
11333 County Road 2
Middlebury, IN 46540

NEF-150MR
20V-757

Subject: Stove Saddle Valves may Leak Gas

Dear Mr. Mccarthy:

This letter serves to acknowledge Grand Design RV, LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

GRAND DESIGN/TRANSCEND/2020

Mfr's Report Date: December 8, 2020

NHTSA Campaign Number: 20V-757

Components:

EQUIPMENT:APPLIANCE:MICROWAVE/OVEN

Potential Number of Units Affected: 352

Problem Description:

Grand Design RV, LLC (Grand Design) is recalling certain 2020 Transcend recreational trailers. A gas leak may occur at the joint between the cook stove's gas saddle valve for the burners and the manifold under the burner surface.

Consequence:

A gas leak increases the risk of a fire.

Remedy:

Grand Design will notify owners, and dealers will install a remedy kit that includes gaskets, washers, thread locker bolts and orange stickers, free of charge. The recall is expected to begin January 20, 2021. Owners may contact Grand Design customer service at 1-574-825-9679. Grand Design's number for this recall is 910022.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

We have received Grand Design's proposed owner notification letter and have approved it for distribution.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Michelle Rice who may be reached by phone at (202) 366-1060, or by email at michelle.rice@dot.gov. We look forward to working with you.

Sincerely,



Joshua Neff
Chief, Recall Management Division
Office of Defects Investigations
Enforcement