#### OMB Control No.: 2127-0004

# Part 573 Safety Recall Report

## 21V-169

**Manufacturer Name:** Nissan North America, Inc.

NHTSA Recall No.: 21V-169
Manufacturer Recall No.: PC798



#### **Manufacturer Information:**

Manufacturer Name: Nissan North America, Inc.

Address: P. O. BOX 685001

Franklin TN 37068-5009

Company phone: 800-647-7261

## **Population:**

Number of potentially involved: 126,809 Estimated percentage with defect: 1 %

#### **Vehicle Information:**

Vehicle 1: 2019-2020 Nissan Altima

Vehicle Type: LIGHT VEHICLES

Body Style : 4-DOOR Power Train : GAS

Descriptive Information: This issue affects certain Nissan Altima and Titan models equipped with the subject

Continental tires shown in the table in the attached Part 573 report.

According to CTA Defect Information Report #21T-001, 203 affected tires were shipped to OEM and Replacement market customers. CTA has informed Nissan that it shipped seven (7) of these tires to Nissan among 3,497 tires molded with the specific DOT and Mold numbers under recall. Nissan has identified 126,809 vehicles that may

have been fitted with these subject tires.

According to CTA Defect Information Report #21T-001, the forecasted incident rate based on the seven (7) tires shipped to Nissan potentially containing the defect is

0.2%.

Production Dates: MAY 20, 2019 - SEP 19, 2020

VIN Range 1 : Begin : NR End : NR Not sequential

Vehicle 2: 2018-2021 Nissan Titan

Vehicle Type: LIGHT VEHICLES Body Style: PICKUP TRUCK

Power Train: GAS

Descriptive Information: This issue affects certain Nissan Altima and Titan models equipped with the subject

Continental tires shown in the attached Part 573 report.

According to CTA Defect Information Report #21T-001, 203 affected tires were shipped to OEM and Replacement market customers. CTA has informed Nissan that it shipped seven (7) of these tires to Nissan among 3,497 tires molded with the specific DOT and Mold numbers under recall. Nissan has identified 126,809 vehicles that may

have been fitted with these subject tires.

According to CTA Defect Information Report #21T-001, the forecasted incident rate based on the seven (7) tires shipped to Nissan potentially containing the defect is

0.2%.

Production Dates: MAY 09, 2018 - FEB 12, 2021

## **Description of Defect:**

Description of the Defect: Please see CTA Defect Information Report #21T-001.

The affected Nissan Altima and Titan vehicles may be equipped with the subject tires. According to CTA, the affected tires in the recall may have a potential over cure condition. As a result, the affected tires may experience a carcass break in the sidewall with sudden air loss, or they could develop a belt adds convention that could lead to a portion of all treed (helt loss).

edge separation that could lead to a partial or full tread/belt loss.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: Affected tires may experience a sudden air loss without warning while others

may exhibit localized tread wear which may manifest as excessive vibration and/or bulging in the tread area. These conditions could increase the risk of

serious injury or death.

Description of the Cause: NR

Identification of Any Warning Affected tires may experience a sudden air loss without warning while others

that can Occur: may exhibit localized tread wear which may manifest as excessive vibration

and/or bulging in the tread area.

## **Involved Components:**

Component Name 1: Continental Tire

Component Description: 265/70 R18 116S TL Grabber HTS

Component Part Number: 40312 EZ41D

Component Name 2: Continental Tire

Component Description: 275/70 R18 116S TL Grabber APT

Component Part Number: 40312 EZ40C

Component Name 3: Continental Tire

Component Description: 215/60 R16 95H TL ProContact TX

Component Part Number: 40312 6CA1D

Component Name 4: Continental Tire

Component Description: 215/60 R16 95H TL ProContact TX

Component Part Number: 40312 6CA1D

Component Name 5: Continental Tire

Component Description: 275/70 R18 116S TL Grabber APT

Component Part Number: 40312 EZ40C

Component Name 6: Continental Tire

Component Description: 215/60 R16 95H TL ProContact TX

Component Part Number: 40312 6CA1D

Component Name 7: Continental Tire

Component Description: 215/60 R16 95H TL ProContact TX

Component Part Number: 40312 6CA1D

#### **Supplier Identification:**

#### **Component Manufacturer**

Name: Continental Tire the Americas, LLC.

Address: 1830 Macmillan Park Drive

Fort Mill South Carolina 29707

Country: United States

#### **Chronology:**

February 15, 2021 – CTA submitted Defect Information Report #21T-001 to NHTSA and notified Nissan of the recall regarding an over cure condition that occurred on certain tires shipped to OEMs and replacement market customers. CTA subsequently provided information concerning the potential quantity of subject tires shipped to Nissan.

Nissan reviewed production records to identify the production period of potentially affected vehicles based on the information provided by CTA. Nissan determined some of the potentially affected tires were installed on certain Nissan Altima and Titan vehicles.

March 4, 2021 – Based on the foregoing, Nissan decided to conduct a safety recall campaign to inspect, and if necessary, remedy all potentially affected vehicles.

#### **Description of Remedy:**

Description of Remedy Program: Nissan will notify all owners of potentially affected vehicles. Dealers will

inspect the sidewalls of all tires for the specific DOT and mold numbers under Continental recall. If any subject tires are found, the dealer will remove and replace the tires with new ones. All removed tires will be collected and returned to Continental for quality and investigation purposes; after which, Continental will dispose of the tires according to

local regulations.

Nissan will coordinate with CTA concerning the appropriate instructions

for any reimbursement requests.

How Remedy Component Differs NR

from Recalled Component:

Identify How/When Recall Condition NR

was Corrected in Production:

## **Recall Schedule:**

Description of Recall Schedule: Nissan will notify all owners of potentially affected vehicles on April 28,

2021. Dealers will be notified on March 12, 2021.

Planned Dealer Notification Date : MAR 12, 2021 - NR Planned Owner Notification Date : APR 28, 2021 - NR

\* NR - Not Reported