

Part 573 Safety Recall Report

21V-218

Manufacturer Name : Winnebago Towable**Submission Date :** MAR 29, 2021**NHTSA Recall No. :** 21V-218**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Winnebago Towable
Address : 201 14th Street
 Middlebury IN 46540
Company phone : 825-5250

Population :

Number of potentially involved : 60
Estimated percentage with defect : 100 %

Vehicle Information :**Vehicle 1 :** 2020-2020 Winnebago Minnie**Vehicle Type :****Body Style :****Power Train :** NR

Descriptive Information : Production Records. Affected units printed out a 15" trire size. Labels that printed out 14" tire size are not included in this recall

Production Dates : APR 24, 2020 - APR 29, 2020**VIN Range 1 : Begin :** NR **End :** NR Not sequential**Description of Noncompliance :****Description of the Noncompliance :** Non Compliance to 49CFR 567.4 and 49CFR 571.100

Noncompliance : A larger tire size is called out on the "certification label" and the "Tire and Loading Information" label

FMVSS 1 : 110 - Tire selection and rims**FMVSS 2 :** NR

Description of the Safety Risk : A 15" Tire and Rim bolt pattern will not fit on this axle, in installed a modification would have to be made that could cause a safety risk that could lead to a crash, injury or death

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Involved Components :

Component Name 1 : NR

Component Description : NR

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

April 19, 2021 Dealer contacted Winnebago about the label tire size not matching the label.

April 22, 2021 Product Safety was alerted of this issue and determined this is a non-compliance and research for a recall began

April 25, 2021 Submitted 573 report to NHTSA Portal

Description of Remedy :

Description of Remedy Program : The correct labels and instructions will be sent to the owner along with their notice

How Remedy Component Differs from Recalled Component : The correct label will call our 14" tires -vs- 15"

Identify How/When Recall Condition was Corrected in Production : The program was change to print the correct tire size

Recall Schedule :

Description of Recall Schedule : TBD - letters will be mailed out within 60 days

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported