

AMA9 Stop Delivery / Recall
Campaign - Replacing threaded
connections on rear trailing arm

**AMA9 Stop Delivery/Recall campaign – Replacing
threaded connections on rear trailing arm**

IMPORTANT REMINDER

**IT IS A VIOLATION OF FEDERAL LAW FOR DEALERS TO DELIVER TO
CUSTOMERS NEW VEHICLES IN THEIR INVENTORY AFFECTED BY
THIS NOTIFICATION UNTIL THESE VEHICLES ARE REMEDIED.
DEALERS SHOULD NOT SELL, LEASE, RENT, OR LOAN ANY NEW OR
USED VEHICLES IN DEALER INVENTORY AFFECTED BY THIS**

NOTIFICATION PRIOR TO REMEDY. DEALERS GROUNDING LEASE RETURNS SHOULD REMEDY ALL AFFECTED GROUNDED VEHICLES.

Overview

There is a possibility that lock nuts on the rear axle trailing arms may break due to stress corrosion.

A broken lock nut may misalign the rear axle, causing a loss of control.

To avoid this, the lock nuts on the rear axle trailing arms must be replaced with nuts manufactured to specification.

Please arrange for this measure to be carried out on the affected vehicles immediately.

| | |
|-------------------|-------------------|
| Model type | Cayenne (9YA/9YB) |
| Model year | 2021 |
| Number | 1,568 |

Parts required

| Part No. | Designation | Quantity/vehicle | Parts return |
|-----------------|--------------------|-------------------------|---------------------|
| PAF010234 | Hexagon nut | 4 ea. | No |

Ordering required parts

Parts may be ordered as required without the need for a PRMS ticket, at up to 50% of UIO (see attached spreadsheet for affected VINs). Please do not over-order, leaving other dealers without sufficient quantities.

Warranty processing

Scope 1: Replacing clamping nuts on the rear trailing arm

| | |
|--------------|-------------|
| Damage code | AMA9 99 000 |
| Repair code | 2 |
| Working time | 71 TU |

Porsche Mobility

If requested, the mobility of the affected customer can be assured by offering a suitable replacement vehicle.

Please invoice this additional service with the campaign scope via WWS.

Further information

| | |
|-----------------------------|--|
| Work instruction | TI No. 72/21, Group 4, Service, AMA9 |
| Vehicle list and allocation | See PCSS or attached list for reference |
| Technical Information | See PCSS or Aftersales Document Database for reference |

[AMA9 VIN List.xlsx](#) 

37.2 KB

(4 views)

Categories: Recalls, Cayenne, Stop Sale

Tags : [cayenne](#), [recall](#), [year m](#), [ama9](#)

Content and Topics

Your Groups



Your Content



Your Places



Personal

Edit Profile



Change Password



Manage

Admin Console



PPN Administration



Create

Discussion



Files



Document



Collaboration



Document

Blog Post



Poll >

Event >

Photo Album >

Idea >

Space >