OMB Control No.: 2127-0004

Part 573 Safety Recall Report

21V-279

Manufacturer Name: Dennis Eagle Inc.
Submission Date: APR 29, 2021
NHTSA Recall No.: 21V-279
Manufacturer Recall No.: FSI1454



Manufacturer Information:

Manufacturer Name: Dennis Eagle Inc.

Address: 2101 47th Street

Sarasota FL 34234

Company phone: 201 9463

Population:

Number of potentially involved: 35 Estimated percentage with defect: 100 %

Vehicle Information:

Vehicle 1: 2017-2021 Dennis Eagle Elite/Proview Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style : 2-DOOR Power Train : DIESEL

Descriptive Information: We have found out that vehicles should be delivered with a hard copy of the

operators manual, we originally supplied them with a USB memory stick containing

the operators manual but there is no way of displaying this in the cab. More investigation has found we should have been supplying a hard copy of the

maintenance manual as well All 35 vehicles are affected

Production Dates: MAY 01, 2017 - APR 22, 2021

VIN Range 1 : Begin : SEG1ADBC9HW022994 End : SEG1AKBC1KW025349
VIN Range 2 : Begin : 1D92BGCB8HF791001 End : 1D92BGCB8HF791001
VIN Range 3 : Begin : 1D92BGCB0KF791006 End : 1D92BGCB3KF791009
VIN Range 4 : Begin : 1D92BGGB9LG791012 End : 1D92BGCB8LG791024

VIN Range 5 : Begin : 1D92EGGB6MG791025 End : 1D92EGGB6MG791025 VIN Range 6 : Begin : 1D92BGCB1LG791026 End : 1D92BGGB7LG791039

92EGGB6MG791025 ☐ Not sequential 92BGGB7LG791039 ☐ Not sequential

Not sequential

Not sequential

Not sequential

Not sequential

Description of Noncompliance:

Description of the DE Inc have been supplying ProView trucks with a copy of the operators

Noncompliance : manual on a USB memory stick, supplying an electronic version of the manual

is OK if there is means to read it within the truck, as we don't supply anything for this we must supply a hard copy. More investigation has found we should

be supplying a hard copy of the maintenance manual as well.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: None as a hard copy of the Quick Reference Guide is supplied with all trucks

Description of the Cause: NR
Identification of Any Warning NR
that can Occur:

Involved Components:

Component Name 1: NR
Component Description: NR
Component Part Number: NR

Supplier Identification:

Component Manufacturer

Name: NR Address: NR

NR

Country: NR

Chronology:

DE have read the legislation and realise they need to have a hard copy of the operators manual as there is no way of displaying the information provided on the USB memory stick. More investigation has found we should supply a hard copy of the maintenance manual as well.

Description of Remedy:

Description of Remedy Program: Send out hard copies of the operator and maintenance manuals

How Remedy Component Differs N/A

from Recalled Component:

Identify How/When Recall Condition Anything leaving production after the date this case has been raised will was Corrected in Production: have a hard copy of the operators and maintenance manual in the cab

Recall Schedule:

Description of Recall Schedule: Send out hard copies of the operators manual

Part 573 Safety Recall Report

21V-279

Page 3

Planned Dealer Notification Date : MAY 10, 2021 - MAY 17, 2021 Planned Owner Notification Date : MAY 24, 2021 - JUN 14, 2021

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573